

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008347/ACY3Q2**Date:** 04/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00005402200

Claimant Vehicle No : SDG1023T **Insured Vehicle No :** YN2799X

Date of Loss: 26/08/2022 Nature of Claim: TP Claim No: SNM22D206031/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDG1023T**

Make & Model: MERCEDES-BENZ E200, 2.0 (A) Engine No: 26492030323790

Reg. Date: 18/06/2021 (Man. Year: 2020) Chassis No: W1K2130802A892281

Colour: Black Odometer: 24263 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,453.00	306.00	2,147.00	87.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	550.00	1,400.00	71.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,403.00	856.00	3,547.00	80.56
+ GST 7.00/7.00% (\$\$)	308.21	59.92	248.29	80.56
Nett Amount (\$\$)	4,711.21	915.92	3,795.29	80.56

INSPECTION

Date of Assignment: 29/08/2022

Date Inspected: 29/08/2022 Inspected At: BLK 3007 UBI ROAD 1 #01-450
SINGAPORE 408700
Repairer: Jack Cars Enterprise Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2022)
Parts:	M1-COUPE	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDG1023T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,800.00 FL	*- FL
2	1		*REAR BUMPER CHROME GARNISH	Dented	340.00 FL	*340.00 FL
3	1		*CLIPS ,RIVETS & SCREW	Not Necessary	100.00 FS	*- FS
4	1		*REVERSE SENSOR	Not Necessary	320.00 FS	*- FS
					Sub Total (S\$)	2,560.00 340.00
					- List Item Discount on L Items 5.00/10.00% (S\$)	107.00 34.00
					Total Parts (S\$)	2,453.00 306.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	600.00	250.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS KNOCK ,JACK ,WELD ,RESHAPE AND ALIGN ALL AFFECTED PORTIONS	New	500.00	250.00
3	TO CHECK LIGHTING SYSTEM WIRING & REWIRE	New	250.00	0.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	220.00	0.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	180.00	0.00
6	TO REMOVE & REINSTALL SENSORS	New	200.00	50.00
Gross Labour Cost (S\$)			1,950.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >