

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008357/UNY3Q2**Date:** 07/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00000502204

Claimant Vehicle No : SJP7876R **Insured Vehicle No :** XE2587A

Date of Loss: 25/08/2022 Nature of Claim: TP Claim No: SNM22D206029/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP7876R**

Make & Model: TOYOTA ALLION, 1.5 (A) Engine No: 1NZD381415

Reg. Date: 08/04/2009 (Man. Year: 2008) Chassis No: NZT2603043097

Colour: Red Odometer: 187335 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,155.33	4,838.94	3,316.39	40.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	2,070.00	1,800.00	46.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,025.33	6,908.94	5,116.39	42.55
Approved Total (Overridden) (\$\$)		5,500.00		
(\$\$)	12,025.33	5,500.00	6,525.33	54.26
+ GST 7.00/7.00% (\$\$)	841.77	385.00	456.77	54.26
Nett Amount (\$\$)	12,867.10	5,885.00	6,982.10	54.26

INSPECTION

Date of Assignment: 29/08/2022

Date Inspected: 29/08/2022 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2022)
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP7876R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	946.30 FL	*946.30 FL
2	1		*BOOTLID LID LOCK TOP	Twisted	466.40 FL	*466.40 FL
3	1		*BOOTLID WEATHERSTRIP	Twisted	173.25 FL	*173.25 FL
4	1		*BOOTLID OUTER CHROME MOULDING	Scratched / Cracked	268.00 FL	*268.00 FL
5	1		*BOOTLID CENTRE LOGO BADGE	Necessary	77.00 FL	*77.00 FL
6	1		*BOOTLID WEATHERSTRIP	Repeated	235.35 FL	*- FL
7	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	256.84 FL	*- FL
8	1		*REAR BUMPER	Distorted	1,465.00 FL	*1,250.00 FL
9	8		*REAR BUMPER FASTENER CLIPS	Necessary	36.00 FL	*36.00 FL
10	2		*REAR BUMPER REFLECTOR	Not Necessary	160.00 FL	*- FL
11	1		*REAR BUMPER BRACKET	N/S Dented	122.40 FL	*61.20 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Bent	195.80 FL	*97.90 FL
13	1		*REAR END PANEL	Badly Dented	628.00 FL	*628.00 FL
14	1		*REAR END PANEL INNER TRIM	Twisted	168.00 FL	*168.00 FL
15	1		*REAR SPARE TYRE PANEL	Repair	830.60 FL	*- FL
16	1		*REAR LUGGAGE FLOOR TRIMBOARD	Torn	287.00 FL	*287.00 FL
17	2		*TAILLAMP	Cracked	912.00 FL	*912.00 FL
18	6		*TAILLAMP CLIPS	Not Necessary	30.00 FL	*- FL
19	1		*N/S REAR MUDGUARD	Repair	1,256.00 FL	*- FL
20	1		*N/S REAR MUDGUARD INNER TRIM	Torn	733.74 FL	*388.10 FL
21	8		*N/S REAR MUDGUARD INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
22	1		*TAILLAMP HOUSING PANEL N/S	Dented	386.10 FL	*386.10 FL
23	1		*BOOTLID REVERSE CAMERA	Serviceable	380.00 FS	*- FS
24	1		*TUBE REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*REAR WINDSCREEN SEAL	Not Necessary	60.00 FS	*- FS
26	1		*REAR LUGGAGE FLOOR INSULATOR	Not Necessary	120.00 FS	*- FS
27	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
28	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,573.78	6,385.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,418.45	1,546.31
Total Parts (\$\$)	8,155.33	4,838.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	40.00	20.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	0.00
3	TO DROP PETROL TANK ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING	New	80.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS, GARNISH AND OTHER TO ENABLE REPAIR	New	100.00	80.00
5	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	350.00	0.00
6	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
7	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	80.00	60.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	200.00	60.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	1,000.00
10	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ADJUST AND REALIGN THE SAME	New	1,600.00	800.00
Gross Labour Cost (\$\$)			3,870.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >