

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 1145X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	TO REPAIR SEE LABOUR	1,655.10	-
2	BOOTLID REFLECTORS @\$554.80 (CONSISTENT)	NOT NECESSARY	1,109.60	-
1	BOOTLID INNER LOCK (CONSISTENT)	TWISTED / SHORTED	450.10	450.10
1	BOOTLID INNER TRIM (CONSISTENT)	NOT NECESSARY	388.90	-
2	BOOTLID HINGES @\$175.45 (CONSISTENT)	NOT NECESSARY	350.90	-
1	BOOTLID WEATHERSTRIP (CONSISTENT)	TWISTED	228.61	228.61
1	BOOTLID OUTER HANDLE (CONSISTENT)	NOT NECESSARY	588.95	-
1	BOOTLID REAR LOGO (CONSISTENT)	NECESSARY	105.00	86.10
1	BOOTLID 'CAMRY' EMBLEM (CONSISTENT)	NOT NECESSARY	68.80	-
1	BOOTLID 'HYBRID' EMBLEM (CONSISTENT)	NECESSARY	85.00	85.00
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	1,045.10	1,045.10
1	REAR BUMPER LOWER DIFFUSER (CONSISTENT)	DISTORTED	488.50	488.50
1	REAR BUMPER BEAM (CONSISTENT)	BENT	711.10	499.20
2	REAR BUMPER BEAM BRACKETS @\$105.00 (CONSISTENT)	BENT	210.00	210.00
2	REAR BUMPER SIDE RETAINERS @\$72.0 (CONSISTENT)	NECESSARY	144.80	144.80
2	REAR BUMPER REFLECTORS @\$100.70 (CONSISTENT)	NOT NECESSARY	201.40	-
1	REAR BUMPER UNDER COVER (CONSISTENT)	DEFORMED / TWISTED	466.80	381.10
2	REAR BUMPER PDC SENSORS @\$480.00 (CONSISTENT)	SHORTED	1,440.00	858.20
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	850.10	722.10
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	429.10	429.10
2	TAILLAMPS @\$885.10 (CONSISTENT)	CRACKED	1,770.20	1,333.80
2	TAILLAMP LOWER BRACKETS @\$55.90 (CONSISTENT)	NOT NECESSARY	111.80	-
2	TAILLAMP BLACK GARNISHS @\$42.70 (CONSISTENT)	NOT NECESSARY	85.40	-
1	TAILLAMP HOUSING PANEL O/S (CONSISTENT)	TO REPAIR SEE LABOUR	366.50	-
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,148.10	-
1	REAR FLOOR PANEL TOP BOARD (CONSISTENT)	WARPED	520.50	520.10

Report Ref No. CC4/ASM22008358/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FLOOR PANEL TOOLS SPONGE (CONSISTENT)	DEFORMED / TORN	715.10	588.20
2	REAR FENDERS @\$1065.30 (CONSISTENT)	TO REPAIR SEE LABOUR	2,132.60	-
2	REAR FENDER INNER TRIMS @\$566.10 (CONSISTENT)	NOT NECESSARY	1,132.20	-
1	REAR EXHAUST (CONSISTENT)	NOT NECESSARY	882.10	-
1	REAR EXHAUST HEAT SHIELD (CONSISTENT)	NOT NECESSARY	150.70	-
2	REAR EXHAUST MOUNTINGS @\$60.00 (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	115.00	-
1	REAR FENDER UNDER SHIELD O/S (CONSISTENT)	NOT NECESSARY	493.10	-
1	REAR BATTERY HOUSING PANEL O/S (CONSISTENT)	NOT NECESSARY	593.20	-
1	REAR BATTERY SPONGE (CONSISTENT)	NOT NECESSARY	105.20	-
1	REAR BATTERY BRACKET (CONSISTENT)	NOT NECESSARY	108.30	-
1	REAR BATTERY TOP BOARD O/S (CONSISTENT)	NOT NECESSARY	145.10	-
1	REAR ANTENNA SENSOR (CONSISTENT)	CRACKED	166.50	166.50
1	REAR WHEEL HOUSING PANEL O/S (CONSISTENT)	TO REPAIR SEE LABOUR	981.10	-
	LESS 25% DISCOUNT		-5,715.14	-2,059.13
			17,145.42	6,177.38
	SPECIAL NETT ITEMS			
1	SET BOOTLID INNER TRIM CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET REAR BUMPER DIFFUSER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE CAMERA (SN) (CONSISTENT)	NOT NECESSARY	380.00	-
1	SET REAR BUMPER UNDER COVER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET REAR FLOOR PANEL INSULATOR (SN) (CONSISTENT)	NECESSARY	480.00	150.00
1	SET REAR FENDER INNER TRIM CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
	SET REAR FENDER UNDER SHIELD CLIPS O/S (SN) (CONSISTENT)	NOT NECESSARY	50.00	-

Report Ref No. CC4/ASM22008358/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET TAILLAMP CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR LICENCE PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			1,380.00	300.00
	LABOUR			
	TO CHECK WIRING .		50.00	30.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		150.00	80.00
	TO DISMANTLE & REFIX BOOTLID MECHANISM .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR WINDSCREEN .	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX FUEL TANK .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACED REAR REVERSE CAMERA.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR UNDER CARRIAGE .	NOT NECESSARY	250.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX REAR DOOR MECHANISM .	NOT NECESSARY	180.00	-
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM.		180.00	80.00
	TO SPRAY RUST PROOFING.		180.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID,TAILLAMP HOUSING PANEL O/S,REAR FLOOR PANEL,REAR FENDERS AND REAR WHEEL HOUSING PANEL O/S.		3,800.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,100.00
			8,400.00	2,420.00
	GRAND TOTAL		26,925.42	8,897.38

RECOMMENDED COST OF LUMP SUM REPAIRS		7,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22008358/Upa3q2

CHUA KANG SENG

Licensed Appraiser