

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|-----------------|-------|------------------------|--|
| | HSBC LIFE (SING | APORE) PTE LTD | F | Ref: | CC4/ASM22008360/Rpa3q2 | |
| | 10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018 | AY FINANCIAL CENTRE TOWER | Ω | Date: | 05/07/2023 | |
| | ATTN:KHOR SAW | THENG | C | Code: | HSB | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SH 7039B | Veh. Inspected | | PC 5082A | |
| | Policy No. | P2465679 | Coverage (\$) | | 0.00 | |
| | Claim No. | S2M049O3 | Excess (\$) | | 0.00 | |
| | Assign From | | Assign Date | | 26/08/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA HIACE SUPER D.P 3.0 A | c.c | | 2982 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2016 | |
| | Chassis No. | KDH2118007109 | Colour | | GREY | |
| | Odometer | 122081 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | FAIR | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 195 R15C | BRIDGESTONE | | 6 mm | |
| | L/H Front Tyre | 195 R15C | BRIDGESTONE | | 6 mm | |
| | R/H Rear Tyre | 195 R15C | BRIDGESTONE | | 6 mm | |
| | L/H Rear Tyre | 195 R15C | BRIDGESTONE | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 23/08/2022 | Inspection Date | | 30/08/2022 | |
| | Survey held at | WILLIAM AUTO PL | | | | |
| | | BLK 3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL EST. SINGAPORE 677965 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NOR | STIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days | | | | |
| | | | | | | |