



Your Ref: S2M045OI

Date: 14th Sep 2022

Our Ref: CS3/ASM22006296/Evy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Winnie Ho

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBE 5150S

INSURED VEHICLE: XD 9087K

ACCIDENT DATE: 29/06/2022

We thank you for your instruction on 29/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBE 5150S from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles GBE 5150S and XD 9087K.
- c) Final Repair Bill of GBE 5150S from M/s LYS Engineering.
- d) Colour damaged vehicle photographs of GBE 5150S.

Pre-Repair Inspection Date: 01/07/2022 at M/s 7 Soon Lee Street #01-39 Ispace, Singapore 627608,
Repairer: LYS Engineering.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBE 5150S
Make & Model	: Toyota Dyna 150 Manual
Year of Registration	: 2015
Chassis Number	: JTFAT35Y90K204688
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 20 (Twenty) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.