

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22006296/Evy3e2 8 SHENTON WAY #24-01 AXA TOWER 07/07/2022 Date: SINGAPORE 068811 ATTN: HO WINNIE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. XD 9087K GBE 5150S Veh. Inspected Policy No. GA457281 Coverage (\$) 0.00 Claim No. S2M045OI Excess (\$) 0.00 HO WINNIE **Assign Date** 01/07/2022 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA DYNA 150** Make & Model 2982 C.C HIDDEN 2015 Engine No. Year of Reg. JTFAT35Y90K204688 **ORANGE** Chassis No. Colour 273049 KM Odometer Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C YOKOHAMA 4 mm 195 R15C YOKOHAMA L/H Front Tyre 4 mm 195 R15C (D) YOKOHAMA 4/4 mm R/H Rear Tyre 195 R15C (D) YOKOHAMA 4/4 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 29/06/2022 01/07/2022 (03:48 PM) Inspect Date / Time Accident Date 7 SOON LEE STREET #01-39 ISPACE SINGAPORE 627608 Survey held at Repairer LYS ENGINEERING 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

Report Ref No. CS3/ASM22006296/Evy3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000

Estimate Days of Repair

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

5b.

CHEN TSUE YEE

Automotive Assessor

EN TSUE YEE

ESTIMATED NORMAL PERIOD FOR REPAIR:

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

10 Working Days