

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122008367/DNY3E2**Date:** 16/01/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SH8575M**Insured Vehicle No :** GBH2021K

Date of Loss: 28/08/2022

Nature of Claim:

TP

Claim No: CDMFG22001783

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SH8575M**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2G75252

Reg. Date: 19/02/2020 (Man. Year: 2020)

Chassis No: JTDKB3FU003091171

Colour: Blue

Odometer: 479175 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side:

West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side:

West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	59,689.01	26,793.58	32,895.43	55.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,840.00	2,560.00	3,280.00	56.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	65,529.01	29,353.58	36,175.43	55.21
+ GST 8.00/8.00% (S\$)	5,242.32	2,348.29	2,894.03	55.21
Nett Amount (S\$)	70,771.33	31,701.87	39,069.46	55.21

INSPECTION

Date of Assignment: 29/08/2022

Date Inspected: 30/08/2022 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 11.0 days

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$29,353.57

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8575M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY, FRONT DOOR, RH	Repair	1,769.60 FL	*- FL
2	1		*FRONT DOOR HINGE UPPER	Not Necessary	115.22 FL	*- FL
3	1		*FRONT DOOR HINGE LOWER	Not Necessary	127.68 FL	*- FL
4	1		*FRONT DOOR CHECK	Not Necessary	214.93 FL	*- FL
5	1		*FRONT DOOR OUTER MOULDING	Not Necessary	264.04 FL	*- FL
6	1		*FRONT DOOR WEATHER STRIP	Not Necessary	641.06 FL	*- FL
7	1		*FRONT DOOR COMFORT LOGO	Necessary	105.00 FL	*105.00 FL
8	1		*BONNET	Broken / Torn	1,330.70 FL	*1,330.70 FL
9	1		*INSULATOR, HOOD	Torn	557.34 FL	*557.34 FL
10	10		*INSULATOR CLIPS	Necessary	50.40 FL	*50.40 FL
11	1		*BONNET RUBBER	Necessary	49.70 FL	*49.70 FL
12	1		*BONNET CABLE	Not Necessary	74.48 FL	*- FL
13	1		*BONNET HINGE (RH)	Bent	80.78 FL	*80.78 FL
14	1		*BONNET HINGE (LH)	Bent	80.78 FL	*80.78 FL
15	1		*BONNET LOCK	Bent	185.64 FL	*185.64 FL
16	1		*CATCH, HOOD AUXILIARY HOOK	Not Necessary	12.04 FL	*- FL
17	1		*RADIATOR GRILLE	Broken	813.20 FL	*316.87 FL
18	1		*RADIATOR GRILLE EMBLEM	Mtg Cracked	123.20 FL	*79.35 FL
19	1		*RADIATOR GRILLE EMBLEM LOWER GARNISH	Cut	268.30 FL	*120.37 FL
20	1		*FRONT BUMPER COVER G5	Torn	1,322.48 FL	*586.18 FL
21	1		*FRONT BUMPER REINFORCEMENT	Dented	974.96 FL	*716.60 FL
22	2		*FRONT BUMPER REINFORCEMENT ABSORBER LH / RH	Not Necessary	323.96 FL	*- FL
23	2		*FRONT BUMPER LOWER REINFORCEMENT BRACKET LH / RH	Not Necessary	924.00 FL	*- FL
24	1		*ABSORBER, FRONT BUMPER, LOWER REINFORCEMENT	Not Necessary	178.78 FL	*- FL
25	1		*FRONT BUMPER SPONGE	Torn	110.32 FL	*110.32 FL
26	1		*FRONT BUMPER LOWER GRILLE	Broken	208.04 FL	*208.04 FL
27	1		*LAMP ASSY, FOG, RH	Mtg Broken	1,288.00 FL	*961.70 FL
28	1		*FRONT NO. PLATE GARNISH	Broken	138.60 FL	*89.60 FL
29	1		*FRONT BUMPER CLIPS	Necessary	30.80 FL	*30.80 FL
30	1		*FRONT BUMPER SIDE RETAINER LH / RH	N/SNotNecessary/O/SBroken	215.60 FL	*77.00 FL
31	1		*FRONT BUMPER TOP GARNISH	Broken	315.56 FL	*225.40 FL
32	2		*FRONT BUMPER SIDE GARNISH LH / RH	Serviceable	433.80 FL	*- FL
33	1		*COVER, FRONT BUMPER HOLE, LH / RH	O/SDislodged/N/SNotNecessary	79.46 FL	*39.73 FL
34	1		*REINFORCEMENT, FRONT BUMPER LOWER	Broken	330.54 FL	*330.54 FL
35	1		*BRACKET, FRONT BUMPER EXTENSION MOUNTING	Not Necessary	154.56 FL	*- FL
36	2		*SUPPORT FR BUMPER, LH / RH	Not Necessary	228.76 FL	*- FL
37	1		*FRONT BUMPER CENTRE FRAME	Not Necessary	331.66 FL	*- FL
38	2		*BRACKET, FRONT BUMPER SIDE, LH / RH	Not Necessary	230.44 FL	*- FL
39	1		*FRONT CHASSIS MEMBER SIDE COVER (RH)	Not Necessary	196.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*UNIT ASSY, HEADLAMP, LH / RH (LED)	O/SBroken/N/SMtgBroken	9,674.00 FL	*5,470.56 FL
41	2		*HEAD LAMP PANEL (LH/RH)	Dented	672.28 FL	*480.20 FL
42	1		*TOP PANEL CENTRE	Dented	510.97 FL	*364.98 FL
43	1		*TOP PANEL SIDE LH / RH	O/S Dented / N/S Repair	408.52 FL	*204.26 FL
44	1		*BRACE PANEL	Bent	105.28 FL	*105.28 FL
45	2		*BRACKET, HEADLAMP MOUNTING, LH / RH	Not Necessary	71.40 FL	*- FL
46	1		*HEADLAMP BULB	Not Necessary	48.02 FL	*- FL
47	1		*RADIATOR ASSY	Bent	2,578.52 FL	*1,841.80 FL
48	1		*COOLANT	Not Necessary	45.00 FL	*- FL
49	1		*RADIATOR FAN MOTOR ASSY	Broken	1,093.90 FL	*925.82 FL
50	1		*RADIATOR TOP HOSE	Broken	60.24 FL	*60.24 FL
51	1		*RADIATOR SPARE TANK	Mtg Broken	176.12 FL	*176.12 FL
52	2		*RADIATOR BOTTOM MOUNTING	Not Necessary	77.00 FL	*- FL
53	2		*STAY, RADIATOR SUPPORT, LH / RH	Not Necessary	183.96 FL	*- FL
54	2		*DEFLECTOR, RADIATOR SIDE, LH / RH	Not Necessary	233.80 FL	*- FL
55	1		*COVER, RADIATOR SUPPORT OPENING	Not Necessary	315.56 FL	*- FL
56	1		*RESERVE TANK ASSY, RADIATOR W/O CAP	Not Necessary	553.42 FL	*- FL
57	1		*HORN	Socket Broken	157.79 FL	*157.79 FL
58	1		*AIR CLEANER HOUSING ASSY	Cracked / Broken	836.70 FL	*836.70 FL
59	1		*AIR CLEANER HOSE	Not Necessary	86.97 FL	*- FL
60	1		*AIR DUCT	Broken	181.16 FL	*181.16 FL
61	1		*INLET ASSY, AIR CLEANER	Not Necessary	278.88 FL	*- FL
62	1		*AIR DUCT CENTRE	Serviceable	131.64 FL	*- FL
63	1		*CONDENSER ASSY, W/RECEIVER	Bent	1,871.24 FL	*1,336.60 FL
64	1		*AIRCON DISCHARGE HOSE	Broken	541.66 FL	*386.90 FL
65	1		*AIRCON LIQUID HOSE & PIPE	Bent	812.63 FL	*580.45 FL
66	1		*AIRCON HOSE SUCTION	Bent	758.62 FL	*541.87 FL
67	1		*FENDER SUB-ASSY, FRONT RH	Dented	1,323.42 FL	*1,111.93 FL
68	1		*FRONT HOUSING ASSY RH	Repair	1,323.36 FL	*- FL
69	1		*FRONT FENDER SHIELD RH	Torn	277.90 FL	*277.90 FL
70	1		*FRONT FENDER SHIELD CLIP	Necessary	20.86 FL	*20.86 FL
71	1		*FRONT FENDER HYBRID EMBLEM, RH	Necessary	121.10 FL	*86.50 FL
72	1		*BRACKET, FRONT SIDE PANEL, RH	Not Necessary	62.30 FL	*- FL
73	1		*EXTENSION, FRONT FENDER, RH	Not Necessary	66.08 FL	*- FL
74	1		*SEAL, FRONT FENDER TO COWL SIDE, RH	Not Necessary	21.28 FL	*- FL
75	1		*GUSSET, FRONT FENDER APRON, LOWER RH	Not Necessary	48.86 FL	*- FL
76	1		*EXTENSION, FRONT FENDER APRON, FRONT RH	Not Necessary	32.48 FL	*- FL
77	1		*MEMBER, FRONT APRON TO COWL SIDE, UPPER RH	Not Necessary	193.76 FL	*- FL
78	1		*FRONT APRON TO COWL SIDE, LOWER FRT RH	Not Necessary	115.22 FL	*- FL
79	1		*FRONT WINDSCREEN GLASS	Cracked	2,278.22 FL	*1,627.30 FL
80	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	292.04 FL	*208.60 FL
81	1		*ARM, FRONT WIPER, RH	Bent / Distorted	252.14 FL	*252.14 FL
82	1		*BLADE, FRONT WIPER, RH	Not Necessary	207.06 FL	*- FL
83	1		*WIPER TOP GARNISH	Broken	935.65 FL	*686.90 FL
84	1		*WIPER SPARE TANK	Mtg Broken	257.25 FL	*257.25 FL
85	1		*WIPER SPARE TANK MOTOR	Damaged	339.78 FL	*339.78 FL
86	1		*WIPER SPARE TANK FLOAT (NECK)	Torn / Deformed	77.70 FL	*77.70 FL
87	1		*FRONT WHEEL RIM	Not Necessary	2,198.77 FL	*- FL
88	1		*FRONT WHEEL CAP	Not Necessary	246.12 FL	*- FL
89	1		*FRONT WHEEL HUB BEARING	Not Necessary	783.92 FL	*- FL
90	1		*FRONT SUSPENSION LOWER ARM (RH)	Not Necessary	884.66 FL	*- FL
91	1		*FRONT SHOCK ABSORBER (RH)	Not Necessary	557.48 FL	*- FL
92	1		*ABSORBER TOP MOUNTING RH	Not Necessary	274.68 FL	*- FL
93	1		*FRONT DRIVE SHAFT (RH)	Not Necessary	2,469.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	1		*RACK & PINION ASSY	Not Necessary	2,269.82 FL	*- FL
95	1		*BAR, STABILIZER	Not Necessary	493.36 FL	*- FL
96	1		*LINK ASSY, FRONT STABILIZER, RH	Not Necessary	275.52 FL	*- FL
97	1		*KNUCKLE, STEERING, RH	Not Necessary	813.12 FL	*- FL
98	1		*JOINT ASSY, LOWER BALL, FRONT RH	Not Necessary	279.97 FL	*- FL
99	1		*ENGINE MOUNTING (RH)	Dented	535.78 FL	*382.70 FL
100	1		*ENGINE MTG (FRONT)	Not Necessary	244.48 FL	*- FL
101	1		*ENGINE MTG (REAR)	Not Necessary	242.06 FL	*- FL
102	1		*ENGINE TOP COVER	Broken	364.00 FL	*260.00 FL
103	1		*BRAKE MASTER PUMP	Cracked / Damaged	8,930.18 FL	*5,281.20 FL
104	1		*FRONT NO. PLATE }	Bent	35.00 FS	*45.00 FS
105	1		*FRONT NO. PLATE TRIM COVER }	Broken	42.00 FS	*- FS
106	1		*FRONT TYRE (RH)	Not Necessary	302.40 FS	*- FS
107	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
108	1		*FRONT WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
109	1		*BONNET STAND	Bent	285.72 FL	*285.72 FL
110	1		*FRONT LOWER CROSSMEMBER	Bent	500.78 FL	*320.65 FL
111	1		*RADIATOR RETURN HOSE INLET	Torn	160.24 FL	*160.24 FL
112	1		*RADIATOR RETURN HOSE OUTLET	Torn	159.64 FL	*159.64 FL
113	1		*FRONT WINDSCREEN LOWER MOULDING	Necessary	185.45 FL	*185.45 FL
114	1		*WIPER TOP GARNISH PANEL	Dented	1,125.38 FL	*1,125.38 FL
115	1		*ENGINE VALVE COVER	Broken	1,568.58 FL	*1,568.58 FL
116	1		*ENGINE VALVE COVER RUBBER	Necessary	268.85 FL	*268.85 FL
117	1		*HEADLAMP ECU O/S	Mtg Broken	2,176.20 FL	*682.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	74,466.41	35,696.44
- List Item Discount on L Items 20.00/25.00% (\$\$)	14,777.40	8,902.86
Total Parts (\$\$)	59,689.01	26,793.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,400.00
2	SPRAY PAINTING CHARGE	New	1,600.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	0.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	0.00
9	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
10	REMOVE / REFIX RADIATOR	New	90.00	50.00
11	REMOVE / REFIX AIRCON & REFILL GAS	New	130.00	80.00
12	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
13	REMOVE / REFIX STEERING RACK / WHEEL / DR SHAFT	New	150.00	0.00
14	REMOVE / REFIX BRAKE MASTER & BOOSTER PUMP	New	120.00	80.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			5,840.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >