



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 2656C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
2	FRONT FORK TUBE ASSY - L/H	BENT/TWISTED	1,050.00	900.00
2	FRONT FORK TUBE ASSY - R/H	NOT NECESSARY	1,050.00	-
1	FORK UNDER BRACKET	BENT	360.00	360.00
1	FRONT FENDER - L/H	DISTORTED	138.00	138.00
1	FRONT FENDER - L/H (MATT)	DISTORTED	128.00	110.00
1	FRONT WHEEL RIM - L/H	CUT	480.00	480.00
1	FRONT RIM SHAFT	NOT NECESSARY	78.00	-
1	FRONT RIM BEARING	NECESSARY	62.00	62.00
1	FRONT BRAKE DISC	NOT NECESSARY	298.00	-
1	HANDLE-BAR	BENT	228.00	228.00
1	SET HAND GRIP	CUT	48.00	48.00
1	HANDLE BAR ENDS	MISSING	75.00	75.00
1	HEADLAMP ASSY	CRACKED	1,500.00	1,200.00
1	SIDE MIRRORS - L/H	CUT	68.00	68.00
1	BRAKE LEVER	CUT	90.00	90.00
2	FRONT SIGNALS	N/S CRACKED (1PC ONLY)	212.00	75.00
1	FRONT COWLING	CUT	220.00	220.00
1	FRONT COVER - MATT	CUT	215.00	215.00
1	FRONT SIDE COVER - MATT	CUT	120.00	80.00
1	FOOTSTEP LOWER PANEL	CUT	200.00	200.00
1	REAR SIDE FAIRING	CUT	168.00	165.00
2	AIR FILTER COVER	NOT NECESSARY	165.00	-
1	DROVE BELT COVER	CUT	185.00	185.00
2	SIDE STAND	NOT NECESSARY	138.00	-
1	MAIN STAND	CUT	228.00	175.00
	LESS 10% DISCOUNT		-750.40	-507.40
			6,753.60	4,566.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	38.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/AGI22008371/Uqy3m4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NECESSARY	95.00	95.00
1	REAR BOX (SN)	CUT	480.00	300.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
			879.00	395.00
	<b>LABOUR</b>			
	TO PROVIDE TOWING SERVING (LOD) S\$60.00 (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING AND RESET HEADLAMP FORCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR.		450.00	380.00
			1,010.00	380.00
	<b>GRAND TOTAL</b>		<b>8,642.60</b>	<b>5,341.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,200.00</b>

Report Ref No. CS/AGI22008371/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.