

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122008372/UCY3Q2**Date:** 02/03/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SNG2093R **Insured Vehicle No :** GBF8576Y

Date of Loss: 27/08/2022 Nature of Claim: TP Claim No: CDMCG22001787

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG2093R**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: HIDDEN

Reg. Date: 19/07/2022 (Man. Year: 2022) Chassis No: LC0CE4DC6N0091427

Colour: Blue Odometer: 4409 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: CHAO YANG 9 mm Rear Left Side: CHAO YANG 9 mm

Front Right Side: CHAO YANG 9 mm Rear Right Side: CHAO YANG 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,876.93	7,961.80	5,915.13	42.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	2,300.00	1,810.00	44.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,986.93	10,261.80	7,725.13	42.95
Approved Total (Overridden) (S\$)		8,200.00		
Nett Amount (S\$)	17,986.93	8,200.00	9,786.93	54.41

INSPECTION

Date of Assignment: 29/08/2022

Date Inspected: 31/08/2022 Inspected At: 53 Defu Lane 12, Singapore 539144
Repairer: Zoom Autowerks Pte Ltd (Bedok)

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Mar 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG2093R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -RH	Badly Dented	3,257.60 FL	*3,257.60 FL
2	1		*REAR DOOR CHECKER	Not Necessary	162.50 FL	*- FL
3	1		*REAR DOOR GLASS OUTER MOULDING	Bent	205.00 FL	*118.00 FL
4	2		*REAR DOOR HINGES	Not Necessary	177.00 FL	*- FL
5	1		*REAR DOOR INNER TRIM BOARD	Not Necessary	588.90 FL	*- FL
6	1		*REAR DOOR INNER LOCK	Damaged	385.00 FL	*385.00 FL
7	1		*REAR DOOR OUTER HANDLE	Cut / Damaged	292.60 FL	*292.60 FL
8	1		*REAR DOOR REGULATOR	Not Necessary	555.00 FL	*- FL
9	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	485.80 FL	*- FL
10	1		*REAR DOOR WEATHERSTRIP	Necessary	122.20 FL	*122.20 FL
11	1		*REAR BUMPER	Cut	2,185.00 FL	*895.00 FL
12	1		*REAR BUMPER SIDE RETAINER	Bent	98.50 FL	*45.00 FL
13	1		*REAR FENDER -RH	Badly Dented	2,981.60 FL	*2,981.60 FL
14	1		*REAR FENDER INNER SHIELD	Twisted	238.00 FL	*105.00 FL
15	1		*REAR FENDER QUARTER GLASS CHROME MOULDING	Necessary	182.60 FL	*100.00 FL
16	1		*REAR FUEL LID	Repair	544.00 FL	*- FL
17	1		*REAR FUEL NECK	Not Necessary	211.50 FL	*- FL
18	1		*REAR SHOCK ABSORBER	Not Necessary	421.00 FL	*- FL
19	1		*REAR KNUCKLE ARM	Not Necessary	289.50 FL	*- FL
20	1		*REAR TOP ARM	Not Necessary	105.00 FL	*- FL
21	1		*REAR TRAILING ARM	Not Necessary	386.90 FL	*- FL
22	1		*REAR WHEEL HUP WITH BEARING	Not Necessary	332.50 FL	*- FL
23	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
24	1		*REAR FENDER QUARTER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
25	1		*REAR TYRE	Serviceable	450.00 FS	*- FS
26	1		*REAR WHEEL RIM -RH	Cut / Warped	480.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,297.70	8,792.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,420.77	830.20
Total Parts (\$)	13,876.93	7,961.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	200.00	0.00
4	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR	New	150.00	80.00
5	TO REMOVE ,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	200.00	60.00
6	TO APPLY UNDERCOATING	New	200.00	60.00
7	PANEL BEATING	New	1,600.00	1,000.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			4,110.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >