3/7/23, 12:16 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22008380/APA3Q2

07/03/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210055656 **Claimant Vehicle** SGX5202S Insured Vehicle No: SNA3157R No:

Date of Loss: 27/08/2022 Nature of Claim: TP Claim No: 4762272829SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SGX5202S

Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK060672

Reg. Date: 28/05/2018 (Man. Year: 2018) Chassis No: WAUZZZF40JA159895

Colour: Odometer: 69895 km Grey

**Engine Capacity:** 1984 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 205/60 R16 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,762.00	2,506.80	3,255.20	56.49
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,502.00	1,602.00	900.00	35.97
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	8,264.00	4,108.80	4,155.20	50.28
	+ GST 7.00/7.00% (S\$)	578.48	287.62	290.86	50.28
	Nett Amount (S\$)	8,842.48	4,396.42	4,446.06	50.28
	+ Car Rental (3.0 x S	\$150.00/day) (S\$)	450.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	4,848.42		

**INSPECTION** 

Date of Assignment: 31/08/2022

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1 Date Inspected: 31/08/2022 Inspected At:

Singapore 408699

Estimated Period of Repair: 3.0 days

**ADRIAN LING CHEW HSIAO TONG** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,609.00 FS	*2,087.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	480.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	249.00 FS	*198.80 FS
4	1		*REAR BUMPER SPOILER	Deformed	276.00 FS	*220.80 FS
5	2		*REAR BUMPER REFLECTOR -LH /RH	Not Necessary	92.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	1,131.00 FS	*-FS
7	2		*REAR BUMPER UPPER IMPACT BAR GASKET -LH/RH	Not Necessary	32.00 FS	*-FS
8	2		*REAR BUMPER GUIDE SECTION -LH /RH	Not Necessary	52.00 FS	*-FS
9	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*-FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*-FS
11	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
F=Fra	ınchise	part. S=Spcl	Nett.			
				Total Parts (S\$)	5,762.00	2,506.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	r Cost (S\$)	2,502.00	1,602.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >