

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008381/EYA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900066449
Claimant Vehicle No :	SJX6751G	Insured Vehicle No :	SKZ6127L
Date of Loss:	07/08/2022	Nature of Claim:	TP
		Claim No:	6409238109SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX6751G		
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FCAH206949
Reg. Date:	30/06/2010 (Man. Year: 2010)	Chassis No:	KNAFW411MA5255960
Colour:	Black	Odometer:	128986 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,010.02	2,926.04	2,083.98	41.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,420.00	1,400.00	49.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,830.02	4,346.04	3,483.98	44.50
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	7,830.02	3,400.00	4,430.02	56.58
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,942.45		

INSPECTION

Date of Assignment:	01/09/2022		
Date Inspected:	01/09/2022	Inspected At:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	651.00 FL	*651.00 FL
2	1		*REAR BUMPER PAD	Deformed	530.00 FL	*231.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Necessary	38.30 FL	*38.30 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Necessary	38.30 FL	*38.30 FL
5	1		*REAR BUMPER REINFORCEMENT	Damaged	527.00 FL	*304.00 FL
6	1		*REAR BUMPER FOAM	Cracked	174.00 FL	*108.00 FL
7	1		*REAR END PANEL	Dented	452.00 FL	*452.00 FL
8	1		*REAR END PANEL GARNISH	Not Necessary	99.80 FL	*- FL
9	1		*TAIL LAMP RH	Not Necessary	462.60 FL	*- FL
10	1		*BOOT LID	Dented	1,782.00 FL	*948.00 FL
11	1		*BOOT LID WEATHERSTRIP	Not Necessary	99.80 FL	*- FL
12	1		*BOOT LID KIA LOGO	Necessary	38.80 FL	*38.80 FL
13	1		*BOOT LID LOCK	Damaged	186.20 FL	*186.20 FL
14	1		*SPARE TYRE PANEL (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*EXHAUST CHROME	Not Necessary	98.00 FL	*- FL
16	1		*EXHAUST SILENCER (NPA)	Not Necessary	0.00 FL	*- FL
17	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
18	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
19	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	10		*REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	5,527.80	3,225.60
- List Item Discount on L Items 10.00/10.00% (\$\$)		517.78	299.56
	Total Parts (\$\$)	5,010.02	2,926.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,000.00	700.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,200.00	600.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	90.00	60.00
5	TO REMOVE AND REFIT REAR SEATS ,REAR WHEELHOUSE INNER GARNISH,FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS	New	200.00	30.00
6	TO REMOVE AND REPLACE EXHAUST SILENCER	New	250.00	0.00
Gross Labour Cost (\$\$)			2,820.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >