

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008384/EA3Q2**Date:** 16/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800000595
Claimant Vehicle No :	SJB8881S	Insured Vehicle No :	SLV7855X
Date of Loss:	27/08/2022	Nature of Claim:	TP
		Claim No:	5665280460SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB8881S	Engine No:	B4204T272563174
Make & Model:	VOLVO XC60, 2.0 T6 R-DESIGN (A)	Chassis No:	YV1UZA2ACJ1111809
Reg. Date:	12/06/2018 (Man. Year: 2018)	Odometer:	66116 km
Colour:	Blue		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,277.00	9,238.50	2,038.50	18.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,940.00	1,120.00	36.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,337.00	11,178.50	3,158.50	22.03
Approved Total (Overridden) (S\$)		8,900.00		
(S\$)	14,337.00	8,900.00	5,437.00	37.92
+ GST 7.00/7.00% (S\$)	1,003.59	623.00	380.59	37.92
Nett Amount (S\$)	15,340.59	9,523.00	5,817.59	37.92
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		9,923.00		

INSPECTION

Date of Assignment:	05/09/2022		
Date Inspected:	05/09/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	2,895.00 FL	*2,425.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*60.00 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	215.00 FL	*- FL
4	1		*REAR LH FENDER	Badly Dented	3,465.00 FL	*3,465.00 FL
5	1		*REAR LH FENDER SHIELD	Torn	250.00 FL	*205.00 FL
6	1		*REAR LH RIM	Cut	1,450.00 FL	*980.00 FL
7	1		*REAR LH DOOR	Bent / Warped	3,760.00 FL	*3,130.00 FL
8	1		*REAR LH TRIM RUBBER	Not Necessary	48.00 FL	*- FL
9	1		*LH SIDE SKIRT (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR LH FENDER QUARTER GLASS MOULDING	Not Necessary	367.00 FL	*- FL
					Sub Total (\$\$)	12,530.00 10,265.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,253.00 1,026.50
					Total Parts (\$\$)	11,277.00 9,238.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	1,100.00	800.00
2	LABOUR CHARGE	New	1,480.00	800.00
3	QUARTER GLASS SEALANT	New	40.00	40.00
4	QUARTER GLASS LABOUR	New	120.00	100.00
5	REMOVE & REFIX CARPET AND GARNISHES	New	120.00	80.00
6	TUFF COAT	New	100.00	60.00
7	WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (S\$)			3,060.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >