

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22008387/DYA3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_02

Claimant Vehicle No : SJP8676U **Insured Vehicle No :** SMT535P

Date of Loss: 27/08/2022 Nature of Claim: TP Claim No: MFL2022D0004787

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP8676U**
 Make & Model: SUZUKI SWIFT, 1.5 AT ABS AIRBAG 2WD (A) Engine No: M15A1370768
 Reg. Date: 15/04/2009 (Man. Year: 2009) Chassis No: JSAEZC21S00551413
 Colour: Blue Odometer: 175721 km
 Engine Capacity: 1490 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,622.59	1,960.00	26,662.59	93.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,920.00	860.00	5,060.00	85.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,542.59	2,820.00	31,722.59	91.84
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	34,542.59	2,000.00	32,542.59	94.21
+ GST 8.00/8.00% (S\$)	2,763.41	160.00	2,603.41	94.21
Nett Amount (S\$)	37,306.00	2,160.00	35,146.00	94.21
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		2,626.45		

INSPECTION

Date of Assignment: 29/08/2022

Date Inspected: 30/08/2022 Inspected At:

Estimated Period of Repair: 3.0 days

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
 AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2023)
Parts:	144	SUZUKI SWIFT 1.5 AT ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP8676U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE SUZUKI LOGO	Not Necessary	318.30 FL	*- FL
2	1		*TAILGATE SWIFT EMBLEM	Not Necessary	125.35 FL	*- FL
3	1		*TAILGATE 1.5 EMBLEM	Not Necessary	115.35 FL	*- FL
4	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	335.40 FL	*- FL
5	1		*TAILGATE SWITCH	Not Necessary	188.46 FL	*- FL
6	1		*TAILGATE LOCK	Not Necessary	319.10 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	743.80 FL	*- FL
8	1		*TAILGATE WEATHER STRIP	Not Necessary	212.65 FL	*- FL
9	4		*TAILGATE RUBBER STOPPER	Not Necessary	79.20 FL	*- FL
10	2		*TAIL LAMP L+R	Not Necessary	1,053.30 FL	*- FL
11	2		*TAIL LAMP PANEL L+R	Not Necessary	599.74 FL	*- FL
12	2		*TAIL LAMP BRACKET L+R	Not Necessary	318.00 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	153.46 FL	*- FL
14	2		*REAR NO. PLATE LAMP L+R	Not Necessary	161.50 FL	*- FL
15	2		*REAR BUMPER BRACKET LH / RH	Not Necessary	184.38 FL	*- FL
16	1		*REAR END PANEL	Repair	1,075.85 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	302.74 FL	*- FL
18	1		*REAR END PANEL AIR DUCT	Not Necessary	329.00 FL	*- FL
19	1		*SPARE WHEEL PANEL	Not Necessary	1,475.20 FL	*- FL
20	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	419.48 FL	*- FL
21	2		*SPARE WHEEL QUARTER PANEL LH / RH	Not Necessary	788.58 FL	*- FL
22	1		*SPARE WHEEL TOOL BOX	Not Necessary	401.93 FL	*- FL
23	2		*REAR FENDER L+R	Not Necessary	3,578.00 FL	*- FL
24	2		*REAR FENDER INNER TRIM L+R	Not Necessary	1,964.00 FL	*- FL
25	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	105.29 FL	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	99.26 FL	*- FL
27	1		*REAR BUMPER CARBON PAD	Cracked	1,200.00 FS	*300.00 FS
28	1		*REAR NUMBER PLATE	Bent / Dented	100.00 FS	*25.00 FS
29	1		*TAILGATE	Not Necessary	2,200.00 FS	*- FS
30	1		*TAILGATE #F8 STICKER	Not Necessary	200.00 FS	*- FS
31	1		*TAILGATE MOTUL STICKER	Not Necessary	200.00 FS	*- FS
32	1		*TAILGATE JP STICKER	Not Necessary	200.00 FS	*- FS
33	1		*TAILGATE ACMA STICKER	Not Necessary	200.00 FS	*- FS
34	1		*TAILGATE SUZUKISPORT STICKER	Not Necessary	200.00 FS	*- FS
35	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*TAILGATE STICKER	Not Necessary	500.00 FS	*- FS
37	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
38	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
39	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
42	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
43	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*REAR BUMPER	Distorted / Mtg Cracked	2,000.00 FS	*800.00 FS
45	1		*REAR BUMPER WILWOOD STICKER }	Necessary	200.00 FS	*200.00 FS
46	1		*REAR BUMPER WILWOOD STICKER }		200.00 FS	*- FS

Report was unsubmitted during this print-out.

2/17/23, 4:55 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER SSR STICKER }		200.00 FS	*- FS
48	1		*REAR BUMPER SSR STICKER }		200.00 FS	*- FS
49	1		*REAR BUMPER MK-II R STICKER }		200.00 FS	*- FS
50	1		*REAR BUMPER MK-II R STICKER }		200.00 FS	*- FS
51	1		*REAR BUMPER MEE POK DRY STICKER }		200.00 FS	*- FS
52	1		*REAR BUMPER LOWER LID	Distorted	1,600.00 FS	*400.00 FS
53	1		*REAR BUMPER LOWER LID LAMP	Not Necessary	1,200.00 FS	*- FS
54	1		*REAR EXHAUST PIPE	Not Necessary	2,000.00 FS	*- FS
55	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					30,167.32	1,960.00
- List Item Discount on L Items 10.00/10.00% (S\$)					1,544.73	0.00
Total Parts (S\$)					28,622.59	1,960.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	400.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	400.00
4	TO TUFF COAT DAMAGED AREAS	New	200.00	20.00
5	TO RNR REVERSE CAMERA	New	100.00	0.00
6	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	New	250.00	0.00
7	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
10	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
11	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
Gross Labour Cost (S\$)			5,920.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >