

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1376Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER BRACKET LH	CUT	35.00	35.00
1	FRONT BUMPER	DEFORMED	481.10	481.10
1	FRONT BUMPER CENTRE UPPER MOULDING	NOT NECESSARY	368.50	-
1	FRONT BUMPER GRILLE LH	SCRATCHED	186.50	186.50
1	FRONT DAY LIGHT LH	NOT NECESSARY	642.50	-
1	FRONT FENDER SHIELD LH	DEFORMED	164.70	164.70
1	FRONT FENDER LH	BUCKLED	588.80	588.80
1	FRONT FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRONT WING MIRROR LH	CUT	1,391.70	1,391.70
1	HEAD LAMP LH	CUT	2,110.30	2,110.30
1	FRONT WHEEL COVER LH	CUT	364.40	364.40
	LESS 20% DISCOUNT		-1,272.02	-1,069.82
			5,088.08	4,279.28
	NETT ITEMS			
1	FRONT DOOR COMFORT LOGO STICKER (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
	<u>LABOUR</u>			
	PANEL BEATING.		850.00	700.00
	SPRAY PAINT.		800.00	750.00
	RESET WHEEL ALIGNMENT.		60.00	60.00
	CHECK LIGHTING.		60.00	30.00
	TOWING FEE.		60.00	-
			1,830.00	1,540.00
	GRAND TOTAL		6,985.58	5,886.78





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,700.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC22008392/Gqce2

XING GUO QIANG

**Automotive Assessor** 

M.MATAI, AMSAE-A

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.