

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS/AIS22008398/RVY3Q2**Date:** 12/12/2022**REFERENCE**

Insured/Claimant: EC SOLUTIONS &amp; ENGINEERING PTE. LTD Policy No: SP2001895872-01

Date of Loss: 23/08/2022

Nature of Claim: OD

Claim No: 202222006409SL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMX909Z**  
 Make & Model: MERCEDES-BENZ GLC300, 2.0 AMG LINE M-HYBRID (A) Engine No: 26492080062272  
 Reg. Date: 26/05/2022 (Man. Year: 2020) Chassis No: W1N2539842V248759  
 Colour: Grey Odometer: 6462 km  
 Engine Capacity: 1991 cc  
 Market Value/New Car Price: S\$272,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,255.00	1,837.00	418.00	18.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	530.00	350.00	180.00	33.96
Paintwork Labour	660.00	350.00	310.00	46.97
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,445.00</b>	<b>2,537.00</b>	<b>908.00</b>	<b>26.36</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>600.00</b>	<b>-600.00</b>	
<b>(S\$)</b>	<b>3,445.00</b>	<b>1,937.00</b>	<b>1,508.00</b>	<b>43.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>241.15</b>	<b>135.59</b>	<b>105.56</b>	<b>43.77</b>
<b>Nett Amount (S\$)</b>	<b>3,686.15</b>	<b>2,072.59</b>	<b>1,613.56</b>	<b>43.77</b>

**INSPECTION**

Date of Assignment: 30/08/2022 Present Location: Vin's Motor Pte Ltd (Sin Ming)  
 Date Inspected: 30/08/2022 Inspected At: 160 SIN MING DRIVE #08-09  
 Estimated Period of Repair: 3.0 days Repairer: Vin's Motor Pte Ltd (Sin Ming)

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 12 Dec 2022)	
<b>Parts:</b>	N/A	MERCEDES-BENZ GLC300 2.0 AMG LINE M-HYBRID (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMX909Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH taillamp	Cracked	380.00 F	*380.00 F
2	1		*LH tailgate reflector	Not Necessary	380.00 F	*- F
3	1		*Rear bumper	Deformed	550.00 F	*550.00 F
4	1		*Rear bumper LH reflector	Scratched	30.00 F	*30.00 F
5	1		*Rear bumper centre pad	Scratched	480.00 F	*480.00 F
6	1		*Rear bumper LH side retainer	Cracked	110.00 F	*110.00 F
7	1		*Rear bumper LH parking sensor	Scratched	120.00 F	*120.00 F
						F=Franchise part.
					<b>Sub Total (\$\$)</b>	<b>2,050.00</b>
					<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	<b>205.00</b>
					<b>Total Parts (\$\$)</b>	<b>2,255.00</b>
						<b>1,837.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO SPRAY PAINTING	New	480.00	250.00
<u>Labour Items</u>				
2	TO REPAIR DAMAGES	New	380.00	250.00
<u>Supplementary #1</u>				
<u>Paintwork Labour</u>				
3	TO SPRAY PAINT REAR LH TAILLAMP PANEL	New	180.00	100.00
<u>Labour Items</u>				
4	TO REPAIR REAR LH TAILLAMP PANEL	New	150.00	100.00
Gross Labour Cost (S\$)			1,190.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >