

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS/AIS22008399/ECY3E2**Date:** 13/10/2022**REFERENCE**

Insured/Claimant: TEO ENG GUAN ANDY Policy No: SP2001902660  
Date of Loss: 26/08/2022 Nature of Claim: OD Claim No: 202222006362JK

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SML373G**  
Make & Model: MERCEDES-BENZ C180, 1.5 (A) Engine No: 27491030864602  
Reg. Date: 08/06/2017 (Man. Year: 2016) Chassis No: WDD2050402R255481  
Colour: Silver Odometer: 92693 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: S\$115,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm  
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,203.05	3,443.48	2,759.57	44.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	2,260.00	680.00	23.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,143.05</b>	<b>5,703.48</b>	<b>3,439.57</b>	<b>37.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	640.01	399.24	240.77	37.62
<b>Nett Amount (S\$)</b>	<b>9,783.06</b>	<b>6,102.72</b>	<b>3,680.34</b>	<b>37.62</b>

**INSPECTION**

Date of Assignment: 30/08/2022

Date Inspected: 30/08/2022 Inspected At:

Cycle & Carriage Automotive Pte Ltd  
188 Pandan Loop  
Singapore 128378

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2022)
<b>Parts:</b>	143	MERCEDES-BENZ C180 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML373G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH/F HEADLAMP	Cut	3,443.48 FS	*3,443.48 FS
2	1		*FRT BUMPER	Repair	1,674.18 FS	*- FS
3	1		*LH/F BUMPER BRACKET	Not Necessary	15.08 FS	*- FS
4	1		*LH/F BASIC MOUNTING FOR BUMPER	Not Necessary	100.40 FS	*- FS
5	1		*LH/F OUTER PARKING SENSOR	Not Necessary	195.43 FS	*- FS
6	1		*LH/F PARKING SENSOR	Not Necessary	195.43 FS	*- FS
7	2		*LH/F PARKING SENSOR SEAL	Not Necessary	14.20 FS	*- FS
8	1		*FRT CROSS MEMBER	Not Necessary	473.91 FS	*- FS
9	1		*LH/F CROSS MEMBER BRACKET	Not Necessary	90.94 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>6,203.05</b>
						<b>3,443.48</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
3	REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH	New	1,440.00	960.00
4	RESPRAY FRONT BUMPER	New	1,000.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,940.00</b>	<b>2,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >