

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008400/KQY3Q2**Date:** 04/10/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961975
Claimant Vehicle No :	SMM9407D	Insured Vehicle No :	SLT2566Z
Date of Loss:	27/08/2022	Nature of Claim:	TP
		Claim No:	283456

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM9407D	Engine No:	2NR5375903
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3901182659
Reg. Date:	19/07/2019 (Man. Year: 2019)	Odometer:	166814 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,556.14	5,428.71	3,127.43	36.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	2,900.00	2,640.00	47.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,096.14	8,328.71	5,767.43	40.91
Approved Total (Overridden) (S\$)		6,650.00		
Nett Amount (S\$)	14,096.14	6,650.00	7,446.14	52.82

INSPECTION

Date of Assignment:	30/08/2022	
Date Inspected:	30/08/2022	Inspected At: Kang Auto Engineering Pte Ltd 160 Sin Ming Drive, #02-16, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	12.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM9407D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	965.20 FL	*924.00 FL
2	1		*BONNET LOCK	Repair	310.00 FL	*- FL
3	1		*BONNET HINGE	Repair	165.00 FL	*- FL
4	1		*FRONT BUMPER	Bent	780.00 FL	*486.10 FL
5	1		*FRONT BUMPER BRACKETS	Repair	85.00 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINER	Serviceable	50.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	225.00 FL	*225.00 FL
8	1		*FRONT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
9	1		*FRONT BRACE PANEL	Repair	195.00 FL	*- FL
10	1		*FRONT GRILLE	Cracked	380.20 FL	*310.50 FL
11	1		*FRONT BADGE	Necessary	60.00 FL	*60.00 FL
12	1		*BOOTLID	Bent	992.20 FL	*778.90 FL
13	1		*BOOTLID EMBLEM	Necessary	54.20 FL	*54.20 FL
14	1		*BOOTLID VIOS BADGE	Necessary	45.17 FL	*45.17 FL
15	1		*BOOTLID E BADGE	Necessary	49.73 FL	*49.73 FL
16	1		*BOOTLID RUBBER	Distorted / Dented	186.50 FL	*186.50 FL
17	1		*SET BOOTLID HINGES	Repair	65.70 FL	*- FL
18	1		*BOOTLID LOCK	Dented	122.01 FL	*122.01 FL
19	1		*REAR END PANEL	Bent	888.10 FL	*781.10 FL
20	1		*REAR END PANEL TOP GARNISH	Distorted	298.60 FL	*205.60 FL
21	1		*REAR BUMPER	Bent	799.50 FL	*522.10 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
23	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	178.14 FL	*89.07 FL
24	2		*REAR BUMPER LOWER LID BRACKETS	Repair	116.00 FL	*- FL
25	1		*TAILLAMP ASSY	N/S Serviceable /O/SMtgCracked	657.00 FL	*328.50 FL
26	2		*TAILLAMP PANELS	Repair	243.20 FL	*- FL
27	1		*REAR REFLECTORS	O/S Missing	257.40 FL	*101.90 FL
28	1		*REAR UNDER COVER	Serviceable	180.00 FL	*- FL
29	1		*EXHAUST SILENCER (LOCAL REPAIR)	Dented	418.58 FS	*120.00 FS
30	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
31	1		*SET REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
32	1		*SET CAMERA	Serviceable	300.00 FS	*- FS
33	2		*HEADLAMP ASSY	Mtg Cracked	950.00 FL	*950.00 FL
34	1		*REAR FENDER (RH)	Bent	275.60 FL	*275.60 FL
35	1		*REAR BUMPER BEAM	Bent	189.30 FL	*189.30 FL
36	2		*TAILGATE RETAINERS	Not Necessary	80.00 FL	*- FL
37	1		*WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,035.33	7,118.28
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,479.19	1,689.57
Total Parts (\$\$)	8,556.14	5,428.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	30.00	30.00
2	TO REMOVE & REFIX EXHAUST SILENCER	New	80.00	60.00
3	TO APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL	New	120.00	90.00
4	TO PUTTY AND SPRAY PAINT CHARGES	New	2,400.00	1,200.00
5	LABOUR CHARGES	New	1,800.00	1,000.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
7	TO APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL	New	50.00	0.00
8	TO PUTTY AND SPRAY PAINT CHARGES	New	400.00	0.00
9	LABOUR CHARGE	New	500.00	400.00
Gross Labour Cost (S\$)			5,540.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >