Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

violo ilisulance (olligapole) File.

Ltd. 4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Fievel Foo Wenyao Date: 26 Sep 2022

Preliminary Advice

Insured: SLT2566Z

Vehicle No

No

TP Vehicle : SMM9407D

Accident Date : 27/08/2022

Make : TOYOTA VIOS Assignment Date : 30/08/2022

Date of : 30/08/2022 Est. Duration of

Inspection : 30/00/2022 Est. Buration of : 12

Inspection At: KANG AUTO ENGINEERING PTE LTD

160 SIN MING DRIVE, #02-16, SIN MING AUTOCITY

SINGAPORE 575722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 11,804.96 Revised Amount :S\$ 7,014.14 Check Items (Estimated) :S\$ 1,384.35 Total :S\$ 8,398.49

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$

Salvage Value :S\$
Margin for Repair :S\$

Remarks	Re	ma	rks
---------	----	----	-----

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
(X	()	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject toconsistency check, part prices and labour cost.