



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 5604C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER TOP (CONSISTENT)	DEFORMED	1,405.00	1,405.00
1	REAR BUMPER BOTTOM (CONSISTENT)	CUT	1,380.00	650.00
1	REAR BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	87.00	-
1	REAR BUMPER BRACKET LH (CONSISTENT)	NOT NECESSARY	87.00	-
1	REAR BUMPER RETAINER RH (CONSISTENT)	NOT NECESSARY	87.00	-
1	REAR BUMPER BRACKET RH (CONSISTENT)	NOT NECESSARY	87.00	-
1	REAR REFLECTOR LH (CONSISTENT)	CRACKED	198.00	95.00
1	REAR REFLECTOR CENTRE (CONSISTENT)	CRACKED	425.00	335.00
3	REAR BUMPER LOWER GARNISH (CONSISTENT)	CUT	750.00	440.00
1	REAR BUMPER INNER BRACKET LH (CONSISTENT)	NOT NECESSARY	259.00	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	852.00	-
1	REAR END PANEL REINFORCEMENT (CONSISTENT)	BENT	565.00	450.00
1	BOOTLID (CONSISTENT)	NOT NECESSARY	3,750.00	-
	LESS 10% DISCOUNT		-993.20	-337.50
			8,938.80	3,037.50
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	485.00	200.00
1	REAR REVERSE SENSOR WIRE (SN) (CONSISTENT)	BROKEN	580.00	300.00
1	REAR REVERSE SENSOR HOLDER (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			1,225.00	500.00
<u>LABOUR</u>				
	CHECK REAR WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	150.00	-
	DIAGNOSE CHECK ON REVERSE SENSOR.	NOT NECESSARY	400.00	-
	REMOVE AND RENEW REAR REVERSE SENSOR.		120.00	40.00
	PANEL BEATING ON AFFECTED AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,600.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,600.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
			3,970.00	840.00
GRAND TOTAL			14,133.80	4,377.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/ASM22008401/Gcy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.