

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|--|-----------------|-----------------------|--|
| | MS FIRST CAPITA | L INSURANCE LTD | Ref: | CS/FCI22008402/Uqy3e2 | |
| | 36 ROBINSON RO #16-01 CITY HOUS | AD SESINGAPORE 068877 | Date: | 19/10/2022 | |
| | | | Code: | FCI2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SG 1195C | Veh. Inspected | SKG 2976D | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | D22002724MFBP | Excess (\$) | 0.00 | |
| | Assign From | CAROLINE CABRERA | Assign Date | 30/08/2022 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | MERCEDES BENZ C180 (A) | c.c | 1595 | |
| | Engine No. | HIDDEN | Year of Reg. | 2012 | |
| | Chassis No. | WDD2040312A748141 | Colour | BLACK | |
| | Odometer | 87377 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| | General | GOOD | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 225/45 R17 | PIRELLI | 7 mm | |
| | L/H Front Tyre | 225/45 R17 | PIRELLI | 7 mm | |
| | R/H Rear Tyre | 225/45 R17 | PIRELLI | 7 mm | |
| | L/H Rear Tyre | 225/45 R17 | PIRELLI | 7 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 20/08/2022 | Inspection Date | 14/09/2022 | |
| | Survey held at | PROGRESSIVE CAR CARE PTE LTD | | | |
| | | BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716 | | | |
| 5a. | Remarks | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | |
| | • | | | | |