

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22008409/UQY3E2

Date: 20/09/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961776		
Claimant Vehicle No :	SLX2796E	Insured Vehicle No :	SLR8140P		
Date of Loss:	28/08/2022	Nature of Claim:	TP	Claim No:	283451

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX2796E	Engine No:	L15B5462579
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81202222
Reg. Date:	01/06/2018 (Man. Year: 2018)	Odometer:	83584 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,286.30	3,815.28	2,471.02	39.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,810.00	1,830.00	50.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,926.30	5,625.28	4,301.02	43.33
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	9,926.30	4,500.00	5,426.30	54.67
+ GST 7.00/7.00% (S\$)	694.84	315.00	379.84	54.67
Nett Amount (S\$)	10,621.14	4,815.00	5,806.14	54.67

INSPECTION

Date of Assignment:	30/08/2022	H S Automotives PTE LTD (HQ)
Date Inspected:	30/08/2022 Inspected At:	Blk 2 Kaki Bukit Avenue 2 #01-15 Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Sep 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX2796E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Badly Dented	1,393.00 F	*1,193.40 FL
2	2		*REAR TAIL GATE REFLECTOR L/R	Not Necessary	717.60 F	*- FL
3	1		*REAR TAIL GATE LOGO (H)	Necessary	58.00 F	*38.00 FL
4	1		*REAR TAIL GATE LOGO (SHUTTLE)	Necessary	68.00 F	*68.00 FL
5	1		*REAR TAIL GATE CHROME MOULDING	Not Necessary	137.40 F	*- FL
6	1		*REAR TAIL GATE CHROME MOULDING CLIP	Not Necessary	45.00 FS	*- FS
7	1		*REAR TAIL GATE INNER TRIM BOARD	Torn	358.00 F	*358.00 FL
8	1		*REAR TAIL GATE INNER TRIM BOARD CLIP	Necessary	45.00 FS	*45.00 FS
9	1		*REAR TAIL GATE WEATHER STRIP	Twisted	188.50 F	*188.00 FL
10	1		*REAR TAIL GATE LOCK	Twisted	157.00 F	*157.00 FL
11	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
12	1		*REAR WINDSCREEN RUBBER MOULDING	Necessary	138.00 F	*138.00 FL
13	1		*REAR BUMPER	Dented	1,250.60 F	*936.00 FL
14	2		*REAR BUMPER RETAINER	Necessary	57.00 F	*57.00 FL
15	1		*REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
16	1		*REAR BUMPER TOW COVER	Deformed	47.50 F	*47.50 FL
17	2		*REAR BUMPER REFLECTOR GARNISH	Cracked	116.00 F	*116.00 FL
18	2		*REAR BUMPER REFLECTOR	Cracked	116.00 F	*116.00 FL
19	1		*REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*REAR END PANEL	Dented	610.80 F	*610.80 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	166.50 F	*166.50 FL
22	1		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	45.00 F	*- FL
23	1		*REAR END PANEL ANTENNA (NPA)	Not Necessary	0.00 F	*- FL
24	2		*REAR BUMPER SPONGE L/R	Torn	166.40 F	*166.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,286.30	4,686.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	871.32

Total Parts (\$\$)	6,286.30	3,815.28
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	600.00
2	SPRAY PAINTING	New	1,500.00	900.00
3	REMOVE & REFIX REAR WINDSCREEN	New	180.00	120.00
4	INSTALL REVERSE SENSOR	New	120.00	50.00
5	CHECK WIRING	New	100.00	20.00
6	TRANSFER TAILGATE COMPONENTS	New	120.00	60.00
7	RUST PROOFING	New	120.00	60.00
Gross Labour Cost (\$\$)			3,640.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >