

ASS. REC. BY: *Marcus*

REF:

*CS/MSG 2208409/4943***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*2/5/4500 Cited \$4199.04, 48%.*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



# HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

not added  
30/8/22  
4/c #4500/  
5 days

Vehicle No :

8LX2786E

Make/Model :

HONDA SHUTTLE

CHASSIS NO :

9K81202222

|                                                       |
|-------------------------------------------------------|
| INDEPENDENT SURVEYOR                                  |
| <input checked="" type="checkbox"/> DIRECT SETTLEMENT |

WORK SHOP REPAIRER ESTIMATE

Date:

30.8.22

Estimate cost of repair to the above mentioned

MARKING

UNIT \$

AMOUNT (\$S)

NO. QTY List Items

|    |   |                                      |            |    |         |    |         |         |
|----|---|--------------------------------------|------------|----|---------|----|---------|---------|
| 1  | 1 | REAR TAIL GATE                       | 300520     | \$ | 1193.40 | \$ | 1393.00 | ✓       |
| 2  | 2 | REAR TAIL GATE REFLECTOR LAMP X/R    | AT X       | \$ | 358.80  | \$ | 717.60  | X       |
| 3  | 1 | REAR TAIL GATE LOCK (H)              | nm cut tan | \$ | 38.     | \$ | 38.00   | ✓       |
| 4  | 1 | REAR TAIL GATE LOCK (SHUTTLE)        | nm         | \$ | -       | \$ | 68.00   | ✓       |
| 5  | 1 | REAR TAIL GATE CHROME MOLDING        | 11 X       | \$ | -       | \$ | 137.40  | X       |
| 6  | 1 | REAR TAIL GATE CHROME MOLDING CLIP   | 9N         | \$ | -       | \$ | 45.00   | X       |
| 7  | 1 | REAR TAIL GATE INNER TRIM BOARD      | to         | \$ | -       | \$ | 358.00  | ✓       |
| 8  | 1 | REAR TAIL GATE INNER TRIM BOARD CLIP | 9N         | \$ | -       | \$ | 45.00   | 1/45 SW |
| 9  | 1 | REAR TAIL GATE WEATHER STRIP         | 7m         | \$ | 188.    | \$ | 188.50  | ✓       |
| 10 | 1 | REAR TAIL GATE LOCK                  | 7m         | \$ | -       | \$ | 157.00  | ✓       |
| 11 | 1 | REAR WINDSCREEN STAKE                | nm 40      | \$ | -       | \$ | 80.00   | 40.5 SW |
| 12 | 1 | REAR WINDSCREEN RUBBER MOLDING       | nm         | \$ | -       | \$ | 138.00  | ✓       |
| 13 | 1 | REAR BUMPER                          | m          | \$ | 936.    | \$ | 1250.60 | ✓       |
| 14 | 2 | REAR BUMPER RETAINER                 | nm         | \$ | 28.50   | \$ | 57.00   | ✓       |
| 15 | 1 | REAR BUMPER CLIP                     | nm         | \$ | -       | \$ | 45.00   | 45.5 SW |
| 16 | 1 | REAR BUMPER TOW COVER                | nm         | \$ | -       | \$ | 47.50   | ✓       |
| 17 | 2 | REAR BUMPER REFLECTOR GARNISH        | cm         | \$ | 58.00   | \$ | 116.00  | ✓       |
| 18 | 2 | REAR BUMPER REFLECTOR                | cm         | \$ | 58.00   | \$ | 116.00  | ✓       |
| 19 | 1 | REAR BUMPER REVERSE SENSOR           | shut 200   | \$ | -       | \$ | 280.00  | 200     |
| 20 | 1 | REAR BOD PANEL                       | BD         | \$ | -       | \$ | 610.80  | ✓       |

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

\$

SURVEYOR NAME

CONTACT:

EMAIL ADD:

maruschug@k/c auto.com

shuttle

reflector  
garnish



# HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.  
TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM  
ROC: 201907812C

|                      |
|----------------------|
| INDEPENDENT SURVEYOR |
| ✓ DIRECT SETTLEMENT  |

## WORK SHOP REPAIRER ESTIMATE

Vehicle No : 8LX2796E  
Make/Model : HONDA SHUTTLE  
CHASSIS NO : 6K8120222

Date: 30.8.22

Estimate cost of repair to the above mentioned

MARKING

UNIT \$

AMOUNT (\$\$)

NO. QTY List Items

|    |   |                                            |   |    |       |           |   |
|----|---|--------------------------------------------|---|----|-------|-----------|---|
| 1  | 1 | REAR WIND DANIEL TOP SHARKWASH 7m          | ✓ | \$ | -     | \$ 166.50 |   |
| 2  | 1 | REAR WIND DANIEL TOP SHARKWASH CLIP 11 1/2 | ✓ | \$ | -     | \$ 45.00  | X |
| 3  | 1 | REAR WIND DANIEL ANTENNA. 11 X             | ✓ | \$ | -     | \$ NA.    | X |
| 4  | 2 | REAR BUMPER SPRINGS L/R 7m                 | ✓ | \$ | 83.20 | \$ 166.40 | ✓ |
| 5  |   |                                            |   | \$ | -     | \$ -      |   |
| 6  |   |                                            |   | \$ | -     | \$ -      |   |
| 7  |   |                                            |   | \$ | -     | \$ -      |   |
| 8  |   |                                            |   | \$ | -     | \$ -      |   |
| 9  |   | DANIEL BMT Panel beating 600               |   | \$ | -     | \$ 1500.  |   |
| 10 |   |                                            |   | \$ | -     | \$ -      |   |
| 11 |   | SPRAY PAINTING 900                         |   | \$ | -     | \$ 1500.  |   |
| 12 |   | remove & refix rear windscreen             |   | \$ | -     | \$ -      |   |
| 13 |   | REMOVE/REFIX REAR WINDSCREEN. 120          |   | \$ | -     | \$ 180.   |   |
| 14 |   | install reverse sensor                     |   | \$ | -     | \$ -      |   |
| 15 |   | INSTALL REVERSE SENSOR 50                  |   | \$ | -     | \$ 120.   |   |
| 16 |   |                                            |   | \$ | -     | \$ -      |   |
| 17 |   | CHECK WIRING 20                            |   | \$ | -     | \$ 100.   |   |
| 18 |   | TRANSFER TAIL GATE COORDINATES. 60         |   | \$ | -     | \$ 120.   |   |
| 19 |   | RUST PROOFING 60                           |   | \$ | -     | \$ 120.   |   |
| 20 |   |                                            |   | \$ | -     | \$ -      |   |

REMARKS:

|                         |  |
|-------------------------|--|
| NO OF DAYS:             |  |
| AGREED FIGURE/LUMP SUM: |  |
| SURVEYOR NAME           |  |
| EMAIL ADD:              |  |

\$ LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTACT:

P- 4386-60

20%

3485.28

330

1810

5625.28

4500