



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9299E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER, FRONT BUMPER	CRACKED	516.00	516.00
1	FRONT BUMPER SIDE RETAINER RH	CRACKED	80.10	80.10
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	TO REPAIR SEE LABOUR	716.60	-
1	ABSORBER, FRONT BUMPER ENERGY	SERVICEABLE	79.60	-
1	LAMP ASSY, FOG, RH	MTG CRACKED	951.40	951.40
1	UNIT ASSY, HEADLAMP, RH	MTG CRACKED	2,637.60	2,637.60
1	COVER, FRONT BUMPER HOLE, RH	SERVICEABLE	29.30	-
1	JAR ASSY, WINDSHIELD WASHER	DENTED	219.10	219.10
1	GRILLE SUB-ASSY, RADIATOR	SERVICEABLE	346.00	-
1	EMBLEM ASSY, RADIATOR GRILLE	NECESSARY	90.80	90.80
1	GRILLE, RADIATOR, LOWER NO.1	SERVICEABLE	170.10	-
1	FENDER SUB-ASSY, FRONT RH	BENT	977.80	977.80
1	LINER, FRONT FENDER, RH	CRACKED	206.70	206.70
1	FRONT FENDER EMBLEM RH	NECESSARY	54.60	54.60
1	RIM	DENTED	1,900.10	1,900.10
1	KNUCKLE, STEERING, RH	SERVICEABLE	663.40	-
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	BENT	760.10	760.10
1	ABSORBER ASSY, SHOCK, FRONT RH	BENT	438.30	438.30
	LESS 25% DISCOUNT		-2,709.40	-2,208.15
			8,128.20	6,624.45
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT BUMPER CLIP (SN)	NECESSARY	65.00	65.00
1	TYRE (200) (90%) (SN)	PUNCTURE	300.00	180.00
1	FRT NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	120.00	-
1	FRT BUMPER SIDE RETAINER CLIP (SN)	NOT NECESSARY	65.00	-
1	FENDER LINER CLIP (SN)	NECESSARY	75.00	60.00
			625.00	305.00
<b><u>LABOUR</u></b>				
	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	30.00

Report Ref No. CS/AGI22008411/Kvy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,800.00	800.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY, FRONT BUMPER.		2,000.00	500.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF REAR FENDER PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			4,990.00	1,410.00
<b>GRAND TOTAL</b>			<b>13,743.20</b>	<b>8,339.45</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,650.00</b>

Report Ref No. CS/AGI22008411/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.