

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008412/UCY3Q2**Date:** 02/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00051402200
Claimant Vehicle No :	SMM3734Z	Insured Vehicle No :	YP2363J
Date of Loss:	25/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D206030/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM3734Z	Engine No:	R16B21601584
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650GT001276
Reg. Date:	17/05/2017 (Man. Year: 2017)	Odometer:	62155 km
Colour:	Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,382.40	3,207.76	1,174.64	26.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,890.00	1,500.00	44.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,772.40	5,097.76	2,674.64	34.41
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	7,772.40	4,000.00	3,772.40	48.54
+ GST 7.00/7.00% (S\$)	544.07	280.00	264.07	48.54
Nett Amount (S\$)	8,316.47	4,280.00	4,036.47	48.54

INSPECTION

Date of Assignment:	30/08/2022	
Date Inspected:	05/09/2022	Inspected At: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2022)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3734Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	579.50 FL	*579.50 FL
2	1		*FRONT BUMPER SIDE HOLDER -LH /RH	N/S Bent	39.40 FL	*19.70 FL
3	10		*FRONT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH -LH	Grazed	31.20 FL	*31.20 FL
5	1		*HEAD LAMP UNIT -LH	Not Necessary	668.50 FL	*- FL
6	1		*HEAD LAMP LOWER RETAINER -LH	Not Necessary	38.50 FL	*- FL
7	1		*FRONT FENDER -LH	Badly Dented	450.80 FL	*450.80 FL
8	1		*FRONT FENDER COWLING -LH	Not Necessary	68.80 FL	*- FL
9	10		*FRONT FENDER COWLING CLIPS -LH	Not Necessary	39.00 FL	*- FL
10	1		*FRONT FENDER LAMP -LH	Scratched	58.10 FL	*58.10 FL
11	1		*ROCKER PANEL OUTER GARNISH -LH	Repair	143.00 FL	*- FL
12	1		*SIDE MIRROR HOUSING ,GLASS ,MOTOR ASSY LH	Cracked	310.90 FL	*310.90 FL
13	1		*SIDE MIRROR OUTER COVER LH	Cracked	50.10 FL	*50.10 FL
14	1		*FRONT DOOR -LH	Dented / Bent	974.10 FL	*974.10 FL
15	1		*FRONT DOOR STICKER -LH	Necessary	34.20 FL	*34.20 FL
16	1		*FRONT DOOR OUTER CHANNEL MOULDING -LH	Grazed	42.10 FL	*42.10 FL
17	1		*FRONT DOOR RUBBER (ROUND) LH	Cut	85.10 FL	*85.10 FL
18	1		*FRONT DOOR LOWER RUBBER -LH	Necessary	17.00 FL	*17.00 FL
19	1		*FRONT DOOR OUTER DOOR HANDLE -LH	Cracked	390.10 FL	*390.10 FL
20	1		*FRONT DOOR TOP HINGES -LH	Not Necessary	49.00 FL	*- FL
21	1		*FRONT DOOR LOWER HINGES -LH	Not Necessary	49.00 FL	*- FL
22	1		*REAR DOORS -LH	Dented / Bent	740.20 FL	*740.20 FL
23	1		*REAR DOORS RUBBER (ROUND)-LH	Necessary	85.30 FL	*85.30 FL
24	1		*REAR DOORS RUBBER (LOWER)-LH	Necessary	11.20 FL	*11.20 FL
25	1		*SET REAR DOOR STICKER -LH	Necessary	55.60 FL	*55.60 FL
26	1		*REAR DOOR OUTER CHANNEL MOULDING -LH	Not Necessary	43.80 FL	*- FL
27	1		*REAR DOOR TOP HINGES -LH	Not Necessary	49.50 FL	*- FL
28	1		*REAR DOOR LOWER HINGES -LH	Not Necessary	49.50 FL	*- FL
29	1		*FRONT & REAR DOOR PROTECTOR SET -LH (MISSING)	Not Necessary	200.00 FS	*- FS
30	1		*FRONT DOOR HANDLE GASKET -LH	Necessary	36.50 FL	*36.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,428.00	4,009.70
- List Item Discount on L Items 20.00/20.00% (\$)	1,045.60	801.94
Total Parts (\$)	4,382.40	3,207.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	1,000.00	580.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)	New	1,875.00	1,080.00
3	TO CHECK WIRING	New	40.00	20.00
4	TOTTRANSFER 2 DOOR AND DOOR FITTINGS	New	160.00	120.00
5	TO TUFF -KOTE	New	120.00	90.00
6	TO 4 WHEEL ALIGNMENT	New	75.00	0.00
7	TO REMOVE,REFIT FRONT BUMPER SENSOR	New	120.00	0.00
Gross Labour Cost (\$\$)			3,390.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >