

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI22008420/RVY3M4**Date:** 17/10/2022**REFERENCE**

Insured/Claimant: CHEONG SHI YA SHEENA Policy No: DMPCSNA00214662101

Date of Loss: 25/08/2022

Nature of Claim: OD

Claim No: SNM22D206049/C01/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL3618E**
 Make & Model: JAGUAR XF, 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC (A) Engine No: 4032177224DT
 Reg. Date: 30/10/2013 (Man. Year: 2013) Chassis No: SAJAC0565DDU00869
 Colour: Black Odometer: 212302 km
 Engine Capacity: 2179 cc
 Market Value/New Car Price: S\$45,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 245/45 ZR18 Rear Tyre Size: 245/45 ZR18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,690.00	580.00	10,110.00	94.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	151.20	151.20	0.00	0.00
Paintwork Labour	124.42	124.42	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,965.62	855.62	10,110.00	92.20
- Excess (S\$)	1,000.00	1,500.00	-500.00	-50.00
(S\$)	9,965.62	-644.38	10,610.00	106.47
+ GST 7.00/7.00% (S\$)	697.59	0.00	697.59	100.00
Nett Amount (S\$)	10,663.21	-644.38	11,307.59	106.04

INSPECTION

Date of Assignment: 30/08/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)
 Date Inspected: 30/08/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
 6 Marsiling Lane
 Singapore 739145
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Please be informed that insured withdraw claim

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$10,110.00 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2022)

Parts: 143 JAGUAR XF 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL3618E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*PARTS		10,690.00 F	*580.00 F	
					Total Parts (S\$)	10,690.00	580.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	124.42	124.42
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	151.20	151.20
			Gross Labour Cost (S\$)	275.62
				275.62

Report was unsubmitted during this print-out.

< END OF ESTIMATES >