

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22008422/UVY3Q2

Date: 27/10/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00143172104
Claimant Vehicle No :	SJY6008P	Insured Vehicle No :	SKU9798G
Date of Loss:	28/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D206089/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY6008P	Engine No:	L15B71672762
Make & Model:	HONDA CIVIC, 1.5 i-VTEC (A)	Chassis No:	MRHFK4840HT000042
Reg. Date:	17/05/2018 (Man. Year: 2017)	Odometer:	73801 km
Colour:	Grey		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	'GREENTRAC' 7 mm	Rear Left Side:	'GREENTRAC' 7 mm
Front Right Side:	'GREENTRAC' 7 mm	Rear Right Side:	'GREENTRAC' 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,775.84	3,243.36	2,532.48	43.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	850.00	330.00	27.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,955.84	4,093.36	2,862.48	41.15
Approved Total (Overridden) (\$\$)		3,250.00		
	6,955.84	3,250.00	3,705.84	53.28
+ GST 7.00/7.00% (\$\$)	486.91	227.50	259.41	53.28
Nett Amount (\$\$)	7,442.75	3,477.50	3,965.25	53.28

INSPECTION

Date of Assignment:	30/08/2022	
Date Inspected:	16/09/2022	Inspected At: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2022)
Parts:	144	HONDA CIVIC 1.5 i-VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY6008P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (SPORT)	Distorted	1,560.70 FL	*1,560.70 FL
2	1		*REAR BUMPER SIDE HOLDER -LH/RH	O/S Bent	59.60 FL	*29.80 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
4	1		*REAR BUMPER REFLECTOR -RH	Cracked	59.20 FL	*59.20 FL
5	1		*REAR BUMPER REFLECTOR GARNISH-RH	Distorted	430.40 FL	*361.90 FL
6	1		*REAR BUMPER LOWER SPOILER	Torn	896.60 FL	*896.60 FL
7	2		*REAR BUMPER SENSOR	Not Necessary	390.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	225.00 FL	*- FL
9	1		*REAR RIM -RH (CUT)	Not Consistent With The Impact	650.90 FL	*- FL
10	1		*TAIL LAMP -RH	Not Necessary	490.20 FL	*- FL
11	1		*EXHAUST PIPE	Not Necessary	997.10 FL	*- FL
12	1		*EXHAUST TOP MOUNTING	Not Necessary	24.10 FL	*- FL
13	1		*EXHAUST TOP PLATE	Not Necessary	61.50 FL	*- FL
14	1		*REAR FENDER COWLING -RH	Not Necessary	185.50 FL	*- FL
15	10		*REAR FENDER COWLING CLIPS -RH	Not Necessary	43.00 FL	*- FL
16	1		*REAR BUMPER LOWER PROTECTOR	Torn	1,108.00 FL	*1,108.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,219.80	4,054.20
- List Item Discount on L Items 20.00/20.00% (S\$)	1,443.96	810.84
Total Parts (S\$)	5,775.84	3,243.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS REMOVE REPLACE ACCIDENT PARTS	New	500.00	300.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	400.00	400.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO REMOVE ,REFIT REAR GARNISHES TO FACILITATE REPAIR	New	120.00	80.00
5	TO TRANSFER /REPLACE REAR BUMPER SENSORS	New	120.00	50.00
Gross Labour Cost (\$\$)			1,180.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >