

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008424/KVY3Q2**Date:** 07/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00009982200

**Claimant Vehicle  
No :** SLQ7330U**Insured  
Vehicle No :** GBL6557J

Date of Loss: 24/08/2022

Nature of Claim: TP

Claim  
No: SNM22D206112/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLQ7330U**

Make &amp; Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)

Engine No: 2ZR8063582

Reg. Date: 20/07/2017 (Man. Year: 2017)

Chassis No: ZYX102023174

Colour: Metallic Brown

Odometer: 410801 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side: Arivo 5 mm

Rear Left Side:

Yokohama 7 mm

Front Right Side: Arivo 5 mm

Rear Right Side:

Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,310.47	2,470.97	2,839.50	53.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,265.00	1,415.00	52.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,990.47</b>	<b>3,735.97</b>	<b>4,254.50</b>	<b>53.24</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>7,990.47</b>	<b>3,000.00</b>	<b>4,990.47</b>	<b>62.46</b>

**INSPECTION**

Date of Assignment: 30/08/2022

Date Inspected: 19/09/2022 Inspected At:

Lian Her Motors (Ang Mo Kio)  
Blk 5038, Ang Mo Kio Industrial Park 2, #01-405  
Singapore 569541

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2022)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ7330U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE ASSY	Bent	1,250.60 FL	*1,250.60 FL
2	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	95.20 FL	*95.20 FL
3	1		*REAR TAIL-GATE INNER TRIM BOARD	Serviceable	426.50 FL	*- FL
4	1		*REAR TAIL-GATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
5	1		*REAR TAIL-GATE INNER LOCK	Repair	452.70 FL	*- FL
6	1		*REAR TAIL-GATE EMBLEM -HYBRID	Not Necessary	48.90 FL	*- FL
7	1		*REAR TAIL-GATE EMBLEM -C-HR	Not Necessary	45.80 FL	*- FL
8	1		*REAR BOOT RUBBER	Serviceable	205.60 FL	*- FL
9	1		*REAR BUMPER	Buckled	855.60 FL	*545.10 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	483.20 FL	*399.50 FL
11	1		*REAR LOWER BUMPER	Bent	455.70 FL	*455.70 FL
12	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
13	1		*REAR TOW COVER	Serviceable	55.10 FL	*- FL
14	1		*REAR ANTENNA	Cracked	175.20 FL	*175.20 FL
15	1		*REAR END PANEL	Repair	725.70 FL	*- FL
16	1		*REAR END PANEL INNER GARNISH	Serviceable	355.70 FL	*- FL
17	20		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
18	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,987.30	3,201.30
- List Item Discount on L Items 25.00/25.00% (S\$)	1,676.83	730.33
Total Parts (S\$)	5,310.47	2,470.97

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	1,200.00	500.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,200.00	600.00
3	CHECK AND RECONNECT WIRING	New	40.00	15.00
4	TO ANTI-RUST PROOFING	New	120.00	30.00
5	REMOVE/REFIT REAR WINDSCREEN	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,680.00</b>	<b>1,265.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >