

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008426/KCY3Q2**Date:** 03/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00008302200		
Claimant Vehicle No :	SDS6883G	Insured Vehicle No :	PC3494H		
Date of Loss:	28/08/2022	Nature of Claim:	TP	Claim No:	SNM22D206084/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDS6883G</b>	Engine No:	8ARW151754
Make & Model:	TOYOTA LEXUS, 2.0 RX200T AT S/R (A)	Chassis No:	JTJZAMCA802000152
Reg. Date:	22/01/2016 (Man. Year: 2015)	Odometer:	145222 km
Colour:	Metallic Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,262.75	6,865.82	2,396.93	25.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,900.00	1,340.00	41.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,502.75</b>	<b>8,765.82</b>	<b>3,736.93</b>	<b>29.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,502.75</b>	<b>7,000.00</b>	<b>5,502.75</b>	<b>44.01</b>

**INSPECTION**

Date of Assignment:	01/09/2022	
Date Inspected:	30/08/2022	Inspected At: 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722 Repairer:Kang Auto Engineering Pte Ltd (HQ)
Estimated Period of Repair:	7.0 days	

**Adjuster:** KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2023)
Parts:	143	TOYOTA LEXUS 2.0 RX200T AT S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS6883G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE GLASS MOULDING	Necessary	135.00 FL	*135.00 FL
2	1		*TAILGATE	Bent	1,856.50 FL	*1,856.50 FL
3	1		*TAILGATE LOCK	Dented	485.00 FL	*322.40 FL
4	1		*TAILGATE LOCK SENSOR	Serviceable	355.00 FL	*- FL
5	1		*TAILGATE HINGE	Repair	223.00 FL	*- FL
6	1		*TAILGATE LEXUS LOGO	Necessary	55.00 FL	*55.00 FL
7	1		*TAILGATE LEXUS EMBLEM	Necessary	65.00 FL	*65.00 FL
8	1		*TAILGATE RX200t BADGE	Necessary	48.00 FL	*48.00 FL
9	1		*TAILGATE LAMPS	O/S Mtg Cracked/N/SServiceable	1,360.00 FL	*680.00 FL
10	1		*REAR BUMPER	Buckled / Cracked	1,526.00 FL	*1,155.30 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	486.00 FL	*486.00 FL
12	1		*REAR BUMPER SPONGE	Cracked	221.00 FL	*147.80 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	75.00 FL	*75.00 FL
14	2		*REAR BUMPER SIDE RETAINER	Serviceable	72.40 FL	*- FL
15	1		*REAR BUMPER BRACKETS	O/S Distorted	270.00 FL	*135.00 FL
16	1		*REAR END PANEL	Bent	814.00 FL	*814.00 FL
17	1		*REAR END PANEL TOP GARNISH	Serviceable	344.00 FL	*- FL
18	1		*REAR UNDER COVER	Bent	562.30 FL	*562.30 FL
19	1		*REAR UNDER COVER CLIPS	Necessary	128.00 FL	*128.00 FL
20	2		*REAR EXHAUST COVER -CHROME	Bent	230.40 FL	*230.40 FL
21	1		*REAR EXHAUST PIPE	Bent	1,865.40 FL	*1,865.40 FL
22	1		*SET REVERSE SENSOR	Shorted	400.00 FS	*250.00 FS
23	1		*SET CAMERA	Serviceable	300.00 FS	*- FS
24	2		*REAR NUMBER PLATE LAMPS	Serviceable	120.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Dented	60.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,057.00	9,056.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,794.25	2,190.28
Total Parts (\$\$)	9,262.75	6,865.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	30.00	20.00
2	TO REMOVE & REFIX TAILGATE	New	200.00	120.00
3	TO APPLY RUST PROOFING ON REPLACED /REPAIRED PANELS	New	160.00	60.00
4	TO PUTTY AND SPRAY PAINT CHARGES	New	1,500.00	800.00
5	LABOUR CHARGE	New	1,350.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,240.00</b>	<b>1,900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >