10/28/22, 11:56 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI22008428/ECY3Q2

Date: 28/10/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMCG22001822

Claimant Vehicle No: SMN6002C Insured Vehicle No: GBG2389E

Date of Loss: 29/08/2022 Nature of Claim: TP Claim No: CDMCG22001804

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN6002C

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: CZC999400

Reg. Date: 20/08/2019 (Man. Year: 2018) Chassis No: WVWZZZAUZKW048567

Colour: Silver Odometer: 64319 km

Engine Capacity: 1395 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,864.61	4,237.90	626.71	12.88
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,560.00	4,280.00	3,280.00	43.39
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	12,424.61	8,517.90	3,906.71	31.44
	+ GST 7.00/7.00% (S\$)	869.72	596.25	273.47	31.44
	Nett Amount (S\$)	13,294.33	9,114.15	4,180.18	31.44

INSPECTION

Date of Assignment: 30/08/2022

Volkswagen Group Singapore Pte Ltd

Date Inspected: 01/09/2022 Inspected At: 247 ALEXANDRA ROAD

Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Oct 2022)

Parts: N/A ADIVA AD1 200 190cc 3W (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN6002C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	26.71 FS	*-FS
2	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	26.71 FS	*-FS
3	1		*FENDER	Dented	655.47 FS	*655.47 FS
4	1		*CROSS SUPPORT LHS FENDER BRACKET	Necessary	36.54 FS	*36.54 FS
5	2		*RIVETTED CAP NUT	Necessary	5.28 FS	*5.28 FS
6	1		*WHEELHOUSE LINER LHS FENDER LINER (UPPER)	Not Necessary	199.41 FS	*- FS
7	1		*REAR VIEW MIRROR HOUSING	Jammed	687.67 FS	*687.67 FS
8	1		*MIRROR GLASS	Not Necessary	192.07 FS	*- FS
9	1		*MIRROR CAP PRIMED	Repair	181.81 FS	*- FS
10	1		*ALLOY WHEEL BLACK TURNED	Cut	2,849.09 FS	*2,849.09 FS
11	1		*RUBBER VALVE	Necessary	3.85 FS	*3.85 FS
F=Fra	anchise	part. S=SpcI	Nett.	-		
				Total Parts (S\$)	4,864.61	4,237.90
			B			

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	B&P WHEEL ALIGNMENT	New	360.00	360.00
4	R&R RIM & BALANCE	New	50.00	50.00
5	LABOUR	New	2,520.00	840.00
6	SPRAYPAINT	New	3,200.00	1,600.00
7	SPRAY PAINTING WING MIRROR COVER	New	250.00	250.00
8	R&R MIRROR HOUSING	New	420.00	420.00
		Gross Labour Cost (S\$)	7,560.00	4,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >