

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref	CS3/CTI22005439/Rqy3e2-1	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date	e: 03/10/2022	
			Cod	le: CTI	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SJZ 8458E	Veh. Inspected	SKV 3326U	
	Policy No.	DMPCSNW00258362100	Coverage (\$)	0.00	
	Claim No.	SNM22D203941/C02/TANCHC	Excess (\$)	0.00	
	Assign From	JACQUELINE TAN	Assign Date	30/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA LEXUS GS450H A	c.c	3456	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	JTHBC96SX05018598	Colour	BLACK	
	Odometer	280333 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/40Z R18	MICHELIN	6 mm	
	L/H Front Tyre	245/40Z R18	MICHELIN	6 mm	
	R/H Rear Tyre	245/40Z R18	MICHELIN	6 mm	
	L/H Rear Tyre	245/40Z R18	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	03/06/2022	Inspection Date	30/08/2022	
	Survey held at	urvey held at 160 SIN MING DRIVE #06-10 SIN MING AUTOCITY			
	Repairer LIAN HENG PAINTER CO.				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				
	•				