



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 4221D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,100.00	-
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	54.00	-
10	FRONT BUMPER CLIPS	NOT NECESSARY	50.00	-
1	FRONT FENDER RH	DENTED	380.00	380.00
1	HEADLAMP RH	NOT NECESSARY	3,750.00	-
	LESS 20% DISCOUNT		-1,066.80	-76.00
			4,267.20	304.00
	<b><u>LABOUR</u></b>			
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		500.00	200.00
	TO RESPRAY AFFECTED AREAS.		500.00	400.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	30.00
			1,030.00	630.00
	<b>GRAND TOTAL</b>		<b>5,297.20</b>	<b>934.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>934.00</b>

Report Ref No. CS/GAI22008429/Eny3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.