

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22008432/UVY3M4**Date:** 08/09/2022**REFERENCE**

Insured/Claimant:	LOW BOON KENG	Policy No:	D22MPC0002769	
Date of Loss:	27/08/2022	Nature of Claim:	OD	Claim No: MPC2022D0004792

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2960Z		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Engine No:	G4FGHU620782
Reg. Date:	19/09/2017 (Man. Year: 2017)	Chassis No:	KMHD841CMJU542010
Colour:	Red	Odometer:	114356 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,354.64	7,258.64	96.00	1.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,920.00	1,100.00	36.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,374.64	9,178.64	1,196.00	11.53
Approved Total (Overridden) (S\$)		7,300.00		
- Excess (S\$)	850.00	850.00	0.00	0.00
Nett Amount (S\$)	9,524.64	6,450.00	3,074.64	32.28

INSPECTION

Date of Assignment:	30/08/2022		
Date Inspected:	31/08/2022	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Sep 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS2960Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	2,253.80 FL	*2,253.80 FL
2	1		*FRONT BONNET N/S HINGE	Repair	49.00 FL	*- FL
3	15		*FRONT BONNET INSULATOR CLIPS	Necessary	52.50 FL	*52.50 FL
4	1		*FRONT N/S FENDER	Buckled	1,227.00 FL	*1,227.00 FL
5	1		*FRONT N/S FENDER INNER SHIELD	Torn	85.00 FL	*85.00 FL
6	6		*FRONT N/S FENDER INNER SHIELD CLIPS	Necessary	21.00 FL	*21.00 FL
7	1		*FRONT BUMPER	Distorted	474.00 FL	*474.00 FL
8	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
9	1		*FRONT BUMPER N/S SIDE RETAINER	Cracked	38.00 FL	*38.00 FL
10	10		*FRONT BUMPER RIVETS	Necessary	40.00 FL	*40.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	695.00 FL	*695.00 FL
12	1		*FRONT BUMPER SPONGE DAMPER	Torn	110.00 FL	*110.00 FL
13	1		*SET FRONT BUMPER N/S FOG LAMP COMP.	Cracked	365.00 FL	*365.00 FL
14	1		*FRONT BUMPER N/S FOG LAMP GARNISH	Distorted	115.00 FL	*115.00 FL
15	1		*FRONT GRILLE	Cracked	529.00 FL	*529.00 FL
16	6		*FRONT GRILLE CLIPS	Not Necessary	21.00 FL	*- FL
17	1		*FRONT GRILLE RUBBER	Necessary	26.00 FL	*26.00 FL
18	1		*FRONT GRILLE H LOGO EMBLEM	Not Necessary	29.00 FL	*- FL
19	1		*SET N/S HEAR LAMP COMP	Broken	1,198.00 FL	*1,198.00 FL
20	1		*N/S HEAD LAMP LOWER BRACKET	Cracked	28.00 FL	*28.00 FL
21	1		*FRONT SUPPORT PANEL	Cracked	949.00 FL	*949.00 FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Warped	80.00 FL	*80.00 FL
23	6		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	21.00 FL	*- FL
24	1		*AIR INTAKE HOSE	Broken	114.00 FL	*114.00 FL
			AIR INTAKE ASSY INSTEAD HOSE			
25	1		*SET FRONT N/S SIDE MIRROR COMP	Cut/Damaged	638.00 FL	*638.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	9,193.30	9,073.30
- List Item Discount on L Items 20.00/20.00% (S\$)	1,838.66	1,814.66
Total Parts (S\$)	7,354.64	7,258.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	40.00	20.00
2	TO REMOVE & REFIX & TOP UP AIR COND GAS & NECESSARY PARTS	New	130.00	100.00
3	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,350.00	800.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			3,020.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >