

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008433/UVY3Q2**Date:** 07/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00167162103

Claimant Vehicle No : SLX8418H **Insured Vehicle No :** SKM98U

Date of Loss: 29/08/2022 Nature of Claim: TP Claim No: SNM22D206119/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX8418H**

Make & Model: PEUGEOT 2008, 1.2 ACTIVE PURETECH (A) Engine No: 10XK012204263

Reg. Date: 13/04/2018 (Man. Year: 2017) Chassis No: VF3CUHNZTHY148977

Colour: White Odometer: 104593 km

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,754.87	15,141.17	16,613.70	52.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,930.00	3,630.00	1,300.00	26.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,684.87	18,771.17	17,913.70	48.83
Approved Total (Overridden) (S\$)		15,000.00		
Nett Amount (S\$)	36,684.87	15,000.00	21,684.87	59.11

INSPECTION

Date of Assignment: 30/08/2022

Date Inspected: 31/08/2022 Inspected At: Zoom Autowerks Pte Ltd (Bedok)
130 Bedok Reservoir Road, #08-1339
Singapore 470130

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Oct 2022)

Parts: 143 PEUGEOT 2008 1.2 ACTIVE PURETECH (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLX8418H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT HEADLAMPS	Holder Cracked	7,350.00 FL	*4,500.00 FL
2	2		*FRONT HEADLAMP LOWER BRACKETS	Not Necessary	155.00 FL	*- FL
3	1		*FRONT GRILLE	Not Necessary	525.00 FL	*- FL
4	1		*FRONT GRILLE CHROME MOULDING	Cracked	462.00 FL	*355.00 FL
5	1		*FRONT GRILLE LOGO	Not Necessary	147.00 FL	*- FL
6	1		*FRONT BUMPER -TOP	Deformed / Torn	1,050.30 FL	*1,050.30 FL
7	1		*FRONT BUMPER -LOWER	Not Necessary	853.20 FL	*- FL
8	2		*FRONT BUMPER FOG LAMPS	Not Necessary	630.00 FL	*- FL
9	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	271.40 FL	*- FL
10	2		*FRONT BUMPER FOG LAMP CHROME MOULDINGS	Not Necessary	201.40 FL	*- FL
11	1		*FRONT BUMPER INNER SPONGE	Not fitted	285.00 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	630.00 FL	*525.00 FL
13	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	170.00 FL	*- FL
14	2		*FRONT SAFETY BELTS	Not Necessary	4,630.00 FL	*- FL
15	2		*FRONT SEAT BELT GUNS	Not Necessary	1,330.00 FL	*- FL
16	1		*CONDENSER	Punctured	1,270.00 FL	*1,080.00 FL
17	1		*REAR WINDSCREEN INNER SEAL	Necessary	85.00 FL	*85.00 FL
18	1		*REAR TAILGATE	Badly Dented	1,850.00 FL	*1,615.00 FL
19	1		*REAR WEATHERSTRIP	Twisted	284.00 FL	*284.00 FL
20	1		*REAR TAILGATE INNER TRIM BOARD	Deformed / Cracked	312.00 FL	*302.00 FL
21	2		*REAR TAILGATE LAMPS	Not Necessary	1,156.00 FL	*- FL
22	1		*REAR TAILGATE INNER LOCK	Dented / Jammed	245.00 FL	*245.00 FL
23	1		*REAR TAILGATE LOGO	Necessary	85.00 FL	*85.00 FL
24	1		*REAR TAILGATE PEUGEOT EMBLEM	Necessary	68.00 FL	*68.00 FL
25	1		*REAR TAILGATE 2008 EMBLEM	Necessary	85.00 FL	*85.00 FL
26	1		*REAR TAILLAMPS	N/S Cracked	1,172.00 FL	*550.00 FL
27	1		*REAR END PANEL	Badly Dented	865.00 FL	*800.00 FL
28	1		*REAR END PANEL INNER GARNISH	Twisted	192.00 FL	*192.00 FL
29	1		*REAR END PANEL AIR VENT	Not Necessary	42.00 FL	*- FL
30	1		*REAR BUMPER	Distorted	1,455.00 FL	*1,455.00 FL
31	1		*REAR BUMPER -SIDE	N/S Repair / O/S Deformed	1,350.00 FL	*420.00 FL
32	1		*REAR BUMPER REFLECTORS	N/S Not Necessary / O/S Broken	236.00 FL	*115.00 FL
33	1		*REAR BUMPER REINFORCEMENT	Distorted	685.00 FL	*685.00 FL
34	2		*REAR BUMPER SIDE RETAINERS	Cracked	130.00 FL	*130.00 FL
35	1		*REAR BUMPER TOW HOOK COVER	Torn	28.00 FL	*28.00 FL
36	1		*SET REAR BUMPER PDC SENSORS	Shorted	567.00 FS	*200.00 FS
37	1		*REAR BUMPER CENTRE FRAME PAD	Distorted	145.00 FL	*145.00 FL
38	2		*REAR NUMBER PLATE LAMPS	Not Necessary	192.00 FL	*- FL
39	1		*REAR SPARE TYRE BOARD	Warped	482.00 FL	*482.00 FL
40	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	1,485.00 FL	*1,120.00 FL
41	1		*REAR EXHAUST SILENCER	Not Necessary	985.00 FL	*- FL
42	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 FL	*- FL
43	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS
45	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
46	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
47	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
48	1		*REAR REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	35,121.30	16,781.30
- List Item Discount on L Items 10.00/10.00% (\$)	3,366.43	1,640.13
Total Parts (\$)	31,754.87	15,141.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE ,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	180.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE ,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
8	TO APPLY UNDERCOATING	New	200.00	90.00
9	PANEL BEATING	New	2,000.00	1,600.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,600.00
Gross Labour Cost (\$\$)			4,930.00	3,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >