

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008437/AYA3Q2**Date:** 13/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070108828
Claimant Vehicle No :	SGS109M	Insured Vehicle No :	SMT8499H
Date of Loss:	20/08/2022	Nature of Claim:	TP
		Claim No:	8116753036SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS109M		
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Engine No:	A427J557N13B16A
Reg. Date:	29/10/2013 (Man. Year: 2013)	Chassis No:	WBA3A120X0J721415
Colour:	White	Odometer:	90987 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,070.85	9,421.40	8,649.45	47.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,620.00	1,810.00	52.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,500.85	11,041.40	10,459.45	48.65
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	21,500.85	8,800.00	12,700.85	59.07
+ GST 7.00/7.00% (S\$)	1,505.06	616.00	889.06	59.07
Nett Amount (S\$)	23,005.91	9,416.00	13,589.91	59.07
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		10,078.00		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment:	22/08/2022		SM Automotive (HQ)
Date Inspected:	22/08/2022	Inspected At:	756 JURONG WEST STREET 74, #12-60
Estimated Period of Repair:	6.0 days		Singapore 640756

Adjuster: ADRIAN LING

Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,258.00 FL	*1,680.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	956.00 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Cracked	387.00 FL	*155.00 FL
4	1		*FRONT BUMPER FOG LAMP LH	Cracked	489.00 FL	*295.00 FL
5	1		*FRONT BUMPER FOG LAMP OUTER GARNISH LH	Missing	214.00 FL	*152.00 FL
6	1		*FRONT BUMPER SIDE AIR VENT	Deformed	98.00 FL	*98.00 FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	154.00 FL	*154.00 FL
8	1		*FRONT BUMPER LOWER AIR DUCT LH	Not Necessary	154.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Not Necessary	1,422.00 FL	*- FL
10	1		*FRONT FENDER	Distorted	1,244.00 FL	*1,244.00 FL
11	1		*FRONT FENDER INNER COWLING	Torn	245.00 FL	*245.00 FL
12	1		*FRONT HEADLAMP LH	Cut	2,245.00 FL	*2,245.00 FL
13	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	189.00 FL	*- FL
14	1		*FRONT HEADLAMP NOZZLE JET LH	Damaged	311.00 FL	*208.00 FL
15	1		*FRONT HEADLAMP NOZZLE JET COVER LH	Deformed	98.00 FL	*98.00 FL
16	1		*FRONT HEADLAMP NOZZLE JET HOSE LH	Not Necessary	72.00 FL	*- FL
17	1		*FRONT HEADLAMP NOZZLE JET BRACKET LH	Not Necessary	258.00 FL	*- FL
18	1		*FRONT LOWER ARM (FRONT)	Bent	298.00 FL	*298.00 FL
19	1		*FRONT LOWER ARM (REAR)	Bent	367.00 FL	*367.00 FL
20	1		*FRONT SHOCK ABSORBER LH	Bent	477.00 FL	*477.00 FL
21	1		*FRONT KNUCKLER ARM	Damaged	865.00 FL	*865.00 FL
22	1		*FRONT KNUCKLER ARM BEARING	Damaged	260.00 FL	*260.00 FL
23	1		*FRONT STEERING RACK & PINION	Not Necessary	2,346.00 FL	*- FL
24	1		*FRONT ANTI ROLL BAR LINK LH	Not Necessary	96.00 FL	*- FL
25	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	1		*FRONT FENDER INNER COWLING CLIPS LH	Necessary	60.00 FS	*30.00 FS
27	1		*FRONT SPORT RIM LH	Cut	980.00 FS	*680.00 FS
28	1		*FRONT TYRE LH	Not Necessary	380.00 FS	*- FS
29	1		*FRONT BUMPER BEAM	Bent	364.00 FL	*285.00 FL
30	1		*FRONT BUMPER UNDER COVER	Torn	271.00 FL	*130.00 FL
31	1		*FRONT HEADLAMP BALLAST LH	Damaged	489.00 FL	*390.00 FL
32	1		*FRONT HEADLAMP MODULE LH	Not Necessary	658.00 FL	*- FL
33	1		*LH FRONT FOG LAMP BRACKET	Not Necessary	158.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,943.00	10,386.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	872.15	964.60
Total Parts (\$\$)	18,070.85	9,421.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,200.00	600.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	500.00
3	LABOUR FOR REMOVE & RENEW FRONT UNDERCARRIAGE LH	New	500.00	220.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
5	WIRING CHECK	New	80.00	30.00
6	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	New	300.00	40.00
7	TO PERFORM DIAGNOSTIC TEST	New	200.00	150.00
Gross Labour Cost (S\$)			3,430.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >