



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AZ 9389X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET SIDE MIRROR L/R	CUT	168.00	120.00
1	FRONT HANDLE BAR	BENT	220.00	175.00
1	SET FRONT HANDLE BALANCER L/R	CUT	96.00	60.00
1	FRONT HANDLE BAR BRACKET	NOT NECESSARY	148.00	-
2	SET FRONT HANDLE BAR GRIP L/R	NOT NECESSARY	82.00	-
1	FRONT HEAD LAMP ASSY	CRACKED	422.00	422.00
1	FRONT HEAD LAMP STAY	NOT NECESSARY	188.00	-
1	SET FRONT SIGNAL LIGHT L/R	N/S CRACKED	280.00	80.00
1	SET FRONT FORK ASSY	BENT	962.00	800.00
1	FRONT FORK UNDER BRACKET	BENT	165.00	165.00
1	SET STEERING CONE BEARING	JAMMED	92.00	92.00
1	SET FRONT WHEEL AXLE & NUT	BENT	85.00	45.00
1	SET FRONT WHEEL	BENT	385.00	300.00
1	SET FRONT WHEEL BEARING	JAMMED	65.00	30.00
1	SET FRONT WHEEL OIL SEAL	NECESSARY	35.00	20.00
1	FRONT WHEEL CENTRE BUSH	NECESSARY	30.00	15.00
1	SET FRONT WHEEL COLLAR	JAMMED	30.00	15.00
1	FRONT ABS BRAKE DISC	NOT NECESSARY	195.00	-
1	BODY COVERSET 'YAMAHA' LOGO	NECESSARY	48.00	35.00
1	SET BODY BLUE COVER	CRACKED	720.00	350.00
1	SET BODY INNER MATT COVER	CRACKED	480.00	250.00
1	SET FOOTREST BOARD L/R	CRACKED	240.00	180.00
1	SET STEP RUBBER	NOT NECESSARY	98.00	-
	LESS 5% DISCOUNT		-261.70	-
	LESS 10% DISCOUNT		-	-315.40
			4,972.30	2,838.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL TYRE (SN)	NOT NECESSARY	160.00	-
1	SET FRONT WHEEL TUBELESS VALVE (SN)	NECESSARY	45.00	15.00
			205.00	15.00

Report Ref No. CS3/ASM22000466/Evy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TOWING CHARGES.		50.00	50.00
	CHECK WIRING SYSTEM AND LIGHT.		100.00	30.00
	FRONT & REAR WHEEL ALIGNMENT.		160.00	50.00
	TO REPAIR, ALIGN AND BALANCE BODY MAIN FRAME.		450.00	200.00
	LABOUR FOR REPAIR AND REPLACE PARTS.		1,000.00	250.00
			1,760.00	580.00
	GRAND TOTAL		6,937.30	3,433.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CS3/ASM22000466/Evy3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.