

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	F	Ref:	CS3/ASM22000466/Evy3e2
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	[Date:	18/01/2022
	ATTN: LYNN KHON	NG	(Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 7742X	Veh. Inspected		AZ 9389X
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M03QY7	Excess (\$)		0.00
	Assign From	LYNN KHONG	Assign Date		13/01/2022
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX	c.c		155
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	MH3SG4640LJ072260	Colour		BLUE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	120/70-14	MAXXIS		5 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	140/70-14	MAXXIS		5 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	5. General Information				
	Accident Date	11/01/2022	Inspect Date / Ti	ime	13/01/2022 (01:10 PM)
	Survey held at - MOTOR CRAFT 7 SOON LEE STREET #01-18 SINGAPORE 627608				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22000466/Evy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser