



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 3707T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	CRACKED	1,899.00	1,280.00
1	FRONT FORK TUBE ASSY	TO REPAIR SEE LABOUR	15,500.00	-
1	FRONT BRAKE DISC (CAN'T SEE DAMAGE)	NOT NECESSARY	2,400.00	-
1	FRONT SPORT RIM (CAN'T SEE DAMAGE)	NOT NECESSARY	4,000.00	-
1	TOP COWLING	CRACKED	3,950.00	3,490.00
1	LAMPSTAY	BENT	509.00	509.00
1	HEADLAMP	GRAZED	4,250.00	2,080.00
1	N/S SIDE MIRROR	GRAZED	850.00	405.00
1	N/S HANDLE-BAR	BENT	355.00	355.00
1	N/S HANDLE-BAR END	GRAZED	90.00	90.00
1	CLUTCH LEVER	GRAZED	155.00	155.00
1	N/S SIDE FAIRING	GRAZED	2,450.00	2,130.00
1	FRONT N/S FOOTREST	NOT NECESSARY	285.00	-
1	FRONT N/S FOOTREST BRACKET (CAN'T SEE DAMAGE)	NOT NECESSARY	435.00	-
1	GEAR PEDAL (CAN'T SEE DAMAGE)	NOT NECESSARY	385.00	-
1	N/S ENGINE COVER	TO REPAIR SEE LABOUR	455.00	-
	LESS 10% DISCOUNT		-3,796.80	-1,049.40
			34,171.20	9,444.60
<u>SPECIAL NETT ITEMS</u>				
2	FORK OILS (SN)	NECESSARY	40.00	40.00
2	FORK OIL SEALS (SN)	NECESSARY	76.00	76.00
1	SET STEERING CONE (SN)	NECESSARY	180.00	120.00
			296.00	236.00
<u>LABOUR</u>				
	TO PROVIDE TOWING SERVICE.	NOT NECESSARY	50.00	-
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT FORK TUBE ASSY & N/S ENGINE COVER.		600.00	450.00
			730.00	480.00
GRAND TOTAL			35,197.20	10,160.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,100.00

Report Ref No. CS1/LAW22008440/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.