

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008446/KYA3Q2**Date:** 14/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700055330
Claimant Vehicle No :	SMS5929J	Insured Vehicle No :	SLS5581P
Date of Loss:	27/08/2022	Nature of Claim:	TP
		Claim No:	6843479179SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS5929J	Engine No:	A012P203B38K15A
Make & Model:	BMW I8, 1.5 COUPE (A)	Chassis No:	WBY2Z22090V396566
Reg. Date:	28/04/2016 (Man. Year: 2016)	Odometer:	42000 km
Colour:	Matt Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R20	Rear Tyre Size:	245/40 R20
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,274.00	595.00	4,679.00	88.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	650.00	750.00	53.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,674.00	1,245.00	5,429.00	81.35
+ GST 7.00/7.00% (S\$)	467.18	87.15	380.03	81.35
Nett Amount (S\$)	7,141.18	1,332.15	5,809.03	81.35
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,655.15		

INSPECTION

Date of Assignment:	31/08/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	31/08/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	2.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,750.00 FL	*- FL
2	2		*FRONT BUMPER SENSOR	Scratched/Shorted (1PCS ONLY)	1,570.00 FL	*500.00 FL
3	1		*FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
4	1		*FRONT BUMPER WRAPPING	Necessary	120.00 FS	*120.00 FS
					Sub Total (\$)	5,540.00 620.00
					- List Item Discount on L Items 5.00/5.00% (\$)	266.00 25.00
					Total Parts (\$)	5,274.00 595.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST ACCIDENT AREA	New	400.00	150.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	400.00	250.00
3	LABOUR CHARGES TO REMOVE AND REPLACE FRONT BUMPER SENSOR	New	100.00	0.00
4	TO DIAGNOSTIC FAULT CODE (PDC) & RESET MEMORY	New	350.00	250.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	150.00	0.00
Gross Labour Cost (\$\$)			1,400.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >