

ASS. REC. BY:

REF:

A/G/ 2200 8446/K6

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.8/100 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMS 5929J

Yr Regn:

04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

BMW i8

c.c

1499

Colour

Matt Black

A/C:

Insured / Std / NI / NA

Sp. Reading

42000

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBY 28 220 P0V 39 6586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R20

R:

245/40R20

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or

Front

R/Bal.

J

mm

Rear

R/Bal.

J

mm

L/Bal.

J

mm

L/Bal.

J

mm

D.O.A.

27/8/22

D.O.I.

31/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Bt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/10

81245.00

C/L

28/10/22

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Date: 31/08/2022
Vehicle No: SMS5929J
Model: BMW i8 COUPE
Chassis: WBY2Z22090V396566
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SLS5581P
Date of Accident: 27/08/2022
Estimator: VICTOR
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		\$3,750.00
2	FRONT PARKING SENSOR 500	1	\$785.00	\$1,570.00
SUB TOTAL				\$5,320.00
LESS 5%				-\$266.00
PARTS TOTAL				\$5,054.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		\$100.00
S/N TOTAL				\$100.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREA.

\$400.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

\$400.00

LABOUR CHARGES TO REMOVE AND REPLACE FRONT BUMPER SENSOR.

\$100.00

TO DIAGNOSTIC FAULT CODE(PDC) & RESET MEMORY.

\$350.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$150.00

LABOUR TOTAL	\$1,400.00
TOTAL	\$6,554.00

Parts - 745.75
S/N - 120.00
Labour - 750.00
Total - \$1615.75

Not Authorised
Money After Repair
PIR 2 days

81245.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

6A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9910 Fax: (+65) 6481 1011

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OW