

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008447/APA3Q2**Date:** 19/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070028421
Claimant Vehicle No :	SJJ5410X	Insured Vehicle No :	SGC716U
Date of Loss:	27/08/2022	Nature of Claim:	TP
		Claim No:	0399901231SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ5410X	Engine No:	L13A4107050
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61096427
Reg. Date:	17/09/2008 (Man. Year: 2008)	Odometer:	156475 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,019.92	3,818.88	1,201.04	23.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,930.00	1,040.00	35.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,989.92	5,748.88	2,241.04	28.05
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	7,989.92	4,500.00	3,489.92	43.68
+ GST 7.00/7.00% (S\$)	559.29	315.00	244.29	43.68
Nett Amount (S\$)	8,549.21	4,815.00	3,734.21	43.68
+ Car Rental (7.0 x S\$70.00/day + 7.00% GST) (S\$)		524.30		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		5,377.75		

INSPECTION

Date of Assignment:	30/08/2022	
Date Inspected:	30/08/2022	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	710.80 FL	*485.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SCREW	Necessary	20.00 FS	*20.00 FS
4	1		*REAR BUMPER TOW COVER	Missing	60.00 FL	*35.00 FL
5	1		*REAR BODY KIT	Deformed	800.00 FS	*600.00 FS
6	1		*REAR BUMPER N/S AND O/S RETAINER	Necessary	130.60 FL	*62.00 FL
7	1		*REAR TAIL-GATE	Dented	902.30 FL	*902.30 FL
8	1		*REAR TAIL-GATE WEATHERSTRIP	Cut	110.40 FL	*110.40 FL
9	1		*REAR TAIL-GATE FIT EMBLEM	Necessary	70.30 FL	*45.00 FL
10	1		*REAR TAIL-GATE INNER TRIM	Cracked	164.30 FL	*164.30 FL
11	8		*REAR TAIL-GATE INNER TRIM CLIPS	Necessary	24.00 FS	*24.00 FS
12	1		*REAR TAIL-GATE LOCK (UPPER)	Jammed	230.70 FL	*230.70 FL
13	1		*REAR TAIL-GATE LOCK (LOWER)	Not Necessary	71.30 FL	*- FL
14	1		*REAR END PANEL	Dented	345.50 FL	*345.50 FL
15	1		*REAR END PANEL INNER TRIM	Deformed	120.40 FL	*120.40 FL
16	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	12.00 FS	*12.00 FS
17	1		*REAR N/S AND O/S TAIL LAMP	O/S Cracked	820.20 FL	*268.00 FL
18	2		*REAR N/S AND O/S FENDER INNER TRIM	Cracked	740.60 FL	*570.00 FL
19	8		*REAR N/S AND O/S FENDER INNER TRIM CLIPS	Necessary	32.00 FS	*32.00 FS
20	1		*SET REAR REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
21	1		*REAR WINDSCREEN MOULDING	Necessary	210.00 FS	*140.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
23	1		*REAR NUMBER PLATE	Dented	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,915.40	4,486.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	895.48	667.72
Total Parts (\$\$)	5,019.92	3,818.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE STRAIGHTEN AND WELDING	New	1,200.00	800.00
2	TO SPRAY PAINTING	New	1,000.00	800.00
3	TO REMOVE AND REFIT REAR EXHAUST	New	180.00	0.00
4	TO REMOVE AND REFIT REAR TAILGATE	New	100.00	80.00
5	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	TO CHECK FOR FAULT CODE AND RESETTNG	New	150.00	0.00
7	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	60.00	50.00
8	TO CHECK WIRING	New	80.00	30.00
9	TO RE-SEAL ANTI-RUST	New	50.00	50.00
Gross Labour Cost (\$\$)			2,970.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >