

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# SJJ5410X

Model: HONDA FIT 1.3G A

Accident Date

3P: SGC716U (AIG)

Location

TP AIG.
Asher.

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Delint</i>	710.80	485.-	
2	10 pcs	Rear bumper clips <i>ru</i>		30.00	✓
3	2 pcs	Rear bumper screw <i>ru</i>		20.00	✓
4	1 pc	Rear bumper tow cover <i>missing</i>	60.00	35.-	
5	1 pc	Rear body kit <i>Delint</i>		800.00	<i>600.00</i>
6	1 pc	Rear bumper n/s and o/s retainer <i>ru</i>	130.60	62.-	
7	1 pc	Rear tail-gate <i>Dented</i>	902.30	✓	
8	1 pc	Rear tail-gate weatherstrip <i>ct</i>	110.40	✓	
9	1 pc	Rear tail-gate 'FIT' emblem <i>ru</i>	70.30	45.-	
10	1 pc	Rear tail-gate inner trim <i>Cut</i>	164.30	✓	
11	8 pcs	Rear tail-gate inner trim clips <i>ru</i>		24.00	✓
12	1 pc	Rear tail-gate lock (Upper) <i>Tam</i>	230.70	✓	
13	1 pc	Rear tail-gate lock (Lower) <i>ru</i>	71.30	+	
14	1 pc	Rear end panel <i>Dented</i>	345.50	✓	
15	1 pc	Rear end panel inner trim <i>Delint</i>	120.40	✓	
16	4 pcs	Rear end panel inner trim clips <i>ru</i>		12.00	✓
17	1 pc	Rear n/s and o/s tail-lamp <i>o/s cracked</i>	820.20	268.-	
18	2 pcs	Rear n/s and o/s fender inner trim <i>Cut</i>	740.60	570.-	
19	8pcs	Rear n/s and o/s fender inner trim clips <i>ru</i>		32.00	✓
20	1 set	Rear reverse sensor <i>Tam</i>		220.00	<i>200</i>
21	1 pc	Rear windscreen moulding <i>ru</i>		210.00	<i>140</i>
22	1 pc	Rear windscreen sealant <i>ru</i>		60.00	✓
23	1 pc	Rear number plate <i>Dented</i>		30.00	✓
		<i>3338.60</i> S.N. 1148 Sub-Total:	4,477.40	1,438.00	0.00
			20%	0%	0%
		<i>2670.88</i> After Less %:	3,581.92	1438.00	0.00
		Labour			
1		To dismantle, straighten and welding.	1,200.00	<i>800</i>	
2		To spray painting.	1,000.00	<i>800</i>	
3		To remove and refit rear exhaust	180.00	+	
4		To remove and refit rear tailgate <i>fitting</i>	100.00	<i>80</i>	
5		To remove and refit rear windscreen.	150.00	<i>120</i>	
6		To check for FAULT code and resetting	150.00	+	
7		To remove and refit rear reverse sensor.	60.00	<i>50</i>	
8		To check wiring.	80.00	<i>30</i>	
9		To re-seal anti-rust.	50.00	✓	
		Sub-Total:	2,970.00		
		Total:	7,989.92		
		After Less 20%:	6,391.94		

Chan San
Director
DipEng. AMM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

24 hr accident call
3155 4106 ESTIMATEPg1

Mobil 1



Achen
2/5 30/08/22
06 days

total 5748.88
h/s: 4.5K