

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008459/AVCE2**Date:** 11/07/2023**REFERENCE**

Insured/Claimant:	OLIVEIRO GLEN NEVILLE	Policy No:	2100505829-05
Date of Loss:	28/08/2022	Nature of Claim:	OD
		Claim No:	0347627840SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF1520G	Engine No:	CYG017684
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G6HN061552
Reg. Date:	31/03/2017 (Man. Year: 2016)	Odometer:	153384 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,230.00	7,136.32	10,093.68	58.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,772.00	4,297.00	10,475.00	70.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,002.00	11,433.32	20,568.68	64.27
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	31,202.00	10,633.32	20,568.68	65.92
+ GST 8.00/8.00% (\$\$)	2,496.16	850.67	1,645.49	65.92
Nett Amount (\$\$)	33,698.16	11,483.99	22,214.17	65.92

INSPECTION

Date of Assignment:	31/08/2022		
Date Inspected:	30/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER - LH	Distorted	1,560.00 FS	*1,248.00 FS
2	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	107.00 FS	*- FS
3	1	*FRONT DOOR STONE CHIP GUARD - LH	Necessary	135.00 FS	*108.00 FS
4	1	*FRONT FENDER BRACE - LH	Not Necessary	107.00 FS	*- FS
5	1	*FRONT FENDER CLOSING ELEMENT - LH	Damaged	60.00 FS	*47.28 FS
6	1	*FRONT FENDER SEAL STRIP - LH	Not Necessary	23.00 FS	*- FS
7	1	*FRONT WHEEL HOUSING LINER - LH	Torn	310.00 FS	*248.00 FS
8	1	*FRONT WHEEL SPOILER - LH	Not Necessary	294.00 FS	*- FS
9	1	*FRONT WHEEL SPOILER STONE CHIP GUARD - LH	Not Necessary	82.00 FS	*- FS
10	1	*FRONT WHEEL SPOILER ADHESIVE TAPE	Not Necessary	59.00 FS	*- FS
11	1	*FRONT WHEEL SPOILER TRIM BRACKET - LH	Not Necessary	19.00 FS	*- FS
12	1	*WASH WATER RESERVOIR	Deformed	208.00 FS	*166.40 FS
13	1	*FUEL FILLER NECK - RH	Not Necessary	339.00 FS	*- FS
14	1	*WINDSCREEN WASHER SYSTEM PUMP	Not Necessary	138.00 FS	*- FS
15	1	*CORRUGATED PIPE	Not Necessary	93.00 FS	*- FS
16	1	*PUMP	Damaged	172.00 FS	*137.20 FS
17	1	*HOSE	Not Necessary	553.00 FS	*- FS
18	1	*PIPE	Damaged	45.00 FS	*35.92 FS
19	1	*FRONT DOOR - LH	Dented	4,760.00 FS	*3,808.00 FS
20	1	*FRONT DOOR STONE GUARD FILM - LH	Not Necessary	135.00 FS	*- FS
21	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	199.00 FS	*- FS
22	1	*FRONT OUTER DOOR SEAL - LH	Necessary	256.00 FS	*204.80 FS
23	1	*BONDING AGENT	Not Necessary	51.00 FS	*- FS
24	1	*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
25	1	*APPLICATOR	Not Necessary	9.00 FS	*- FS
26	1	*FRONT DOOR UPPER HINGE - LH	Not Necessary	113.00 FS	*- FS
27	4	*FRONT DOOR UPPER AND LOWER THREADED PLATE - LH / RH	Not Necessary	70.00 FS	*- FS
28	1	*FRONT DOOR LOWER HINGE - LH	Not Necessary	113.00 FS	*- FS
29	1	*FRONT EXTERIOR MIRROR MOUNTING - LH	Not Necessary	1,552.00 FS	*- FS
30	1	*FRONT EXTERIOR MIRROR HOUSING - LH	Repair	221.00 FS	*- FS
31	1	*FRONT MIRROR GLASS CARRIER PLATE - LH	Not Necessary	1,298.00 FS	*- FS
32	1	*FRONT TURN SIGNAL INDICATOR - LH	Not Necessary	141.00 FS	*- FS
33	1	*FRONT WINDOW SLOT SEAL TRIM STRIP - LH	Not Necessary	380.00 FS	*- FS
34	1	*ROOF PANEL MOLDING - RH	Not Necessary	571.00 FS	*- FS
35	1	*FRONT WATER DEFLECTOR STRIP - LH	Not Necessary	75.00 FS	*- FS
36	1	*FRONT DOOR WIND - LH	Cut	1,219.00 FS	*975.20 FS
37	1	*ROCKER MOLDING MOUNT KIT	Necessary	93.00 FS	*74.24 FS
38	1	*ROCKER MOLDING TAPE	Necessary	18.00 FS	*14.24 FS
39	1	*FRONT BUMPER STONE GUARD FILM - LH	Not Necessary	133.00 FS	*- FS
40	1	*FRONT FENDER BRACKET - LH	Not Necessary	99.00 FS	*- FS
41	1	*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
42	1	*CAVITY WAX	Not Necessary	140.00 FS	*- FS
43	1	*STONE CHIP	Not Necessary	180.00 FS	*- FS
44	1	*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
45	1	*SUNDRIES	Necessary	500.00 FS	*16.48 FS
46	1	*WASHER PUMP SEAL (Supplementary)	Necessary	66.00 FS	*52.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,230.00 7,136.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
4	TO DISMANTLE AND REINSTALL FRONT BUMPER AND LHS SILL PANEL TRIM. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS A-PILLAR. TO CUT OUT AND WELD LHS A-PILLAR BRACKET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED	New	6,000.00	1,750.00
5	TO RESPRAY LHS FRONT FENDER, BONNET, LHS FRONT DOOR, HINGES, LHS WING MIRROR COVER, LHS SILL PANEL TRIM AND LHS A-PILLAR	New	5,500.00	2,075.00
6	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS	New	400.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			14,772.00	4,297.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >