

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008460/AQCE2**Date:** 04/01/2023**REFERENCE**

Insured/Claimant:	CHAUDHARI AJAY SHOK	Policy No:	7210004265-01	
Date of Loss:	24/08/2022	Nature of Claim:	OD	Claim No: 1153640976SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8267P	Engine No:	DEM025744
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF53MA004285
Reg. Date:	30/01/2021 (Man. Year: 2020)	Odometer:	35150 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$190,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,670.00	285.60	6,384.40	95.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,652.00	3,202.00	5,450.00	62.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,322.00	3,487.60	11,834.40	77.24
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	13,722.00	1,887.60	11,834.40	86.24
+ GST 7.00/7.00% (S\$)	960.54	132.13	828.41	86.24
Nett Amount (S\$)	14,682.54	2,019.73	12,662.81	86.24

INSPECTION

Date of Assignment:	31/08/2022		
Date Inspected:	30/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Repair	3,977.00 FS	*- FS
2	1		*REAR OUTER DOOR SEAL - LH	Not Necessary	247.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	180.00 FS	*- FS
7	1		*REAR DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
8	1		*SIDE MEMBER TRIM - LH	Not Necessary	916.00 FS	*- FS
9	1		*SIDE MEMBER TRIM SECUR ATTACHMENT PARTS	Necessary	136.00 FS	*108.80 FS
10	1		*SIDE MEMBER TRIM ADHESIVE TAPES	Necessary	221.00 FS	*176.80 FS
11	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	49.00 FS	*- FS
12	1		*REAR PARKING AID SENSOR	Not Necessary	266.00 FS	*- FS
13	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

6,670.00

285.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	0.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR LHS REAR FENDER. TO RENEW LHS REAR DOOR AND LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DOOR ENTRANCE, LHS SILL PANEL, LHS REAR DOOR	New	4,500.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,652.00	3,202.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >