

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 786G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (CONSISTENT)	BENT	2,958.50	2,551.00
1	BONNET LOCK (CONSISTENT)	DISTORTED	140.30	140.30
1	BONNET UPPER LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	95.50	-
1	BONNET LOWER LOCK (CONSISTENT)	DISTORTED	126.50	126.50
1	BONNET INNER RUBBER (CONSISTENT)	SERVICEABLE	97.20	-
1	BONNET OUTER RUBBER (CONSISTENT)	SERVICEABLE	48.80	-
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	208.50	-
1	BONNET HINGE (CONSISTENT)	TO REPAIR SEE LABOUR	126.50	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	156.40	156.40
1	FRONT GRILLE CHROME (CONSISTENT)	CRACKED	315.60	315.60
1	FRONT FRILLE EMBLEM (CONSISTENT)	NECESSARY	56.40	56.40
1	FRONT NUMBER PLATE BASE (CONSISTENT)	DENTED	280.60	280.60
1	FRONT BUMPER (CONSISTENT)	BUCKLED	1,975.30	1,280.00
2	FRONT BUMPER SIDE RETAINER (CONSISTENT)	SERVICEABLE	178.80	-
1	FRONT BUMPER LOWER CENTRE GRILLE (CONSISTENT)	SERVICEABLE	135.50	-
1	FRONT BUMPER SPONGE (CONSISTENT)	NO SUCH PARTS	255.80	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	852.20	605.00
2	FRONT BUMPER BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	208.80	-
1	FRONT BUMPER INNER CARRIAGE (CONSISTENT)	SERVICEABLE	288.80	-
2	FRONT BUMPER PROTECTOR (CONSISTENT)	SERVICEABLE	237.60	-
2	FRONT BUMPER SIDE CHROME (CONSISTENT)	NECESSARY	273.70	273.70
1	FRONT BUMPER WIPPER COVER RIGHT (CONSISTENT)	MISSING	182.10	182.10
1	FRONT BUMPER WIPPER NOZZLE RIGHT (CONSISTENT)	MISSING	385.40	385.40
1	FRONT BUMPER WIPPER BRACKET RIGHT (CONSISTENT)	CRACKED	208.10	208.10
1	FRONT SUPPORT PANEL (CONSISTENT)	BENT	1,204.30	640.00
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	NO SUCH PARTS	180.20	-
2	FRONT SUPPORT PANEL SIDE GARNISH (CONSISTENT)	O/S CRACKED	376.80	188.40

Report Ref No. CC4/ASM22008465/Kpa3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT BRACE PANEL (CONSISTENT)	BENT	102.20	102.20
1	INNER COOLER ASSY (CONSISTENT)	PUNCTURE	1,649.10	1,280.00
1	AIR CONDENSER ASSY (CONSISTENT)	PUNCTURE	1,565.20	1,201.70
1	RADIATOR ASSY (CONSISTENT)	PUNCTURE	1,150.80	1,150.80
2	HEADLAMP (CONSISTENT)	MTG CRACKED	6,375.60	2,208.00
2	HEADLAMP TOP PANEL (CONSISTENT)	O/S BUCKLED	347.30	173.65
1	BOOTLID LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	BOOTLID EMBLEM LOGO (CONSISTENT)	NECESSARY	46.10	46.10
1	BOOTLID EMBLEM E200 (CONSISTENT)	NECESSARY	72.80	72.80
1	BOOTLID EMBLEM C&C (CONSISTENT)	NECESSARY	64.20	64.20
1	BOOTLID EMBLEM KOMPRESSOR (CONSISTENT)	NECESSARY	59.20	59.20
1	TAILLAMP LEFT (CONSISTENT)	CRACKED	732.30	589.50
1	TAILLAMP SIDE COVER LEFT (CONSISTENT)	CRACKED	242.70	242.70
1	TAILLAMP INNER PANEL LEFT (CONSISTENT)	TO REPAIR SEE LABOUR	485.40	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	1,842.80	1,495.00
1	REAR BUMPER TOW COVER (CONSISTENT)	MISSING	76.20	76.20
2	REAR BUMPER SIDE RETAINER (CONSISTENT)	O/S DISTORTED	134.20	67.10
1	REAR BUMPER DIFFUSER (CONSISTENT)	SERVICEABLE	328.90	-
4	REAR BUMPER REVERSE SENSOR (CONSISTENT)	SHORTED (2 PCS ONLY)	723.20	361.60
4	REAR BUMPER REVERSE SENSOR HOLDER (CONSISTENT)	SHORTED (2 PCS ONLY)	88.80	44.40
2	REAR BUMPER LOWER RETAINER (CONSISTENT)	MISSING	84.20	84.20
1	REAR BUMPER PROTECTOR (CONSISTENT)	SERVICEABLE	398.80	-
1	REAR BUMPER CENTRE CHROME (CONSISTENT)	DENTED	268.20	220.00
1	REAR BUMPER SIDE CHROME LEFT (CONSISTENT)	NECESSARY	190.40	155.00
1	REAR BUMPER SPONGE (CONSISTENT)	NO SUCH PARTS	246.20	-
2	REAR BUMPER BRACKET (CONSISTENT)	SERVICEABLE	206.80	-
1	REAR BUMPER INNER CARRIAGE (CONSISTENT)	CRACKED	260.80	260.80
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	789.50	775.00
1	REAR END PANEL (CONSISTENT)	BENT	1,205.80	955.00
1	REAR END PANEL INNER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,030.80	-

Report Ref No. CC4/ASM22008465/Kpa3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR END PANEL TOP GARNISH (CONSISTENT)	CRACKED	395.60	205.00
1	SPARE TYRE TOP BOARD (CONSISTENT)	SERVICEABLE	579.80	-
	LESS 10% DISCOUNT		-3,357.26	-1,927.97
			30,215.34	17,351.68
1	BOOTLID WEATHERSTRIP (SN) (CONSISTENT) (50%)	DENTED / DISTORTED	177.70	88.85
	LESS 10% DISCOUNT		-17.77	-
			159.93	88.85
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	BENT	20.00	20.00
1	FRONT NUMBER PLATE HOLDER (SN) (CONSISTENT)	BENT	20.00	20.00
			40.00	40.00
	<u>LABOUR</u>			
	TO REMOVE RENEW & REFIT AIR CONDENSER ASSY TO FACILITATE REPAIR .		300.00	100.00
	TO REMOVE RENEW & REFIT ALL ACCIDENT DAMAGE PARTS CUT & WELD PANEL BEAT & STRAIGHTEN ALL ACCIDENT AREAS & FIT THE ABOVE SAME.INCLUSIVE OF THE REPAIR OF BONNET UPPER LOCK ,BONNET HINGE AND FRONT BUMPER BRACKET.		1,000.00	600.00
	TO PUTTY & SPRAY PAINT ON ALL ACCIDENT DAMAGE PARS & OTHER ACCIDENT AFFECTED AREAS .		1,000.00	660.00
	TO REMOVE RENEW & REFIT ALL ACCIDENT DAMAGE PARTS CUT & WELD PANEL BEAT & STRAIGHTEN ALL ACCIDENT AREAS & FIT THE ABOVE SAME.INCLUSIVE OF THE REPAIR OF BOOTLID LOCK,TAILLAMP INNER PANEL LEFT AND REAR END PANEL INNER PANEL.		1,000.00	700.00
	TO PUTTY & SPRAY PAINT ON ALL ACCIDENT DAMAGE PARS & OTHER ACCIDENT AFFECTED AREAS .		1,000.00	800.00
	TO SPRAY ANTI RUST ON ACCIDENT PANEL.		100.00	90.00
			4,400.00	2,950.00
	GRAND TOTAL		34,815.27	20,430.53



Page No.:4 of 4

RECOMMENDED COST OF LUMP SUM REPAIRS		16,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22008465/Kpa3q2

**KONG SENG CHEONG** 

**Licensed Appraiser**