



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 6123M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP LH (CONSISTENT)	CUT	566.00	566.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	695.00	695.00
2	FRONT BUMPER SIDE BRACKET L/R @\$60.00 (CONSISTENT)	N/S DAMAGED	120.00	60.00
1	FRONT BUMPER REINFORCEMENT BEAM (CONSISTENT)	NOT NECESSARY	238.00	-
1	FRONT FENDER LH (CONSISTENT)	DENTED	479.00	479.00
1	FRONT FENDER INNER SHIELD LH (CONSISTENT)	NOT NECESSARY	127.00	-
1	FRONT KNUCKLE LH (CONSISTENT)	DAMAGED	320.00	320.00
1	FRONT KNUCKLE BEARING LH (CONSISTENT)	DAMAGED	139.00	139.00
1	FRONT LOWER ARM LH (CONSISTENT)	NOT NECESSARY	298.00	-
1	FRONT STABILIZER BAR LH (CONSISTENT)	NOT NECESSARY	135.00	-
	LESS 10% DISCOUNT		-311.70	-225.90
			2,805.30	2,033.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT SPORT RIM LH (SN) (CONSISTENT)	CUT	450.00	400.00
1	FRONT TYRE LH (SN) (CONSISTENT)	NOT NECESSARY	350.00	-
1	FRONT ABSORBER LH (SN) (CONSISTENT)	NOT NECESSARY	600.00	-
1	FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT BUMPER RIVET (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	FRONT BUMPER LOWER LIP (SN) (CONSISTENT)	DEFORMED	500.00	400.00
1	FRONT FENDER INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			2,010.00	860.00
<u>LABOUR</u>				
	TO CHECK REAR WIRING.		80.00	30.00
	TO REMOVE, CHECK & REPLACE FRONT UNDERCARRIAGE PARTS.		380.00	150.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS.		800.00	500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON AFFECTED AREA.		800.00	600.00
			2,210.00	1,360.00
GRAND TOTAL			7,025.30	4,253.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/ASM22008471/Acy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.