

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC22008475/Kvy3m4	
	73 BRAS BASAH R #05-01 NTUC TRAI 189556	OAD DE UNION HOUSESINGAPORE	Date:	02/09/2022	
	ATTN: JEFF LIN		Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKL 8329G	Veh. Inspected	YG 99H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1186122-002	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	31/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI CANTER (M)	c.c	2998	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	FEB21EA20166	Colour	WHITE	
	Odometer	57946 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/85 R15	YOKOHAMA	9 mm	
	L/H Front Tyre	195/85 R15	YOKOHAMA	9 mm	
	R/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	9/9 mm	
	L/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	9/9 mm	
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE REAR N/S & FRONT			
5.	5. General Information				
	Accident Date	26/08/2022	Inspect Date / Time	31/08/2022 ( 10:05 AM )	
	Survey held at	CELEBRITY AUTO			
		BLK 176 SIN MING DRIVE #03-18 SIN MING AUTOCARE SINGAPORE 575721			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC22008475/Kvy3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**