

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22008480/ECY3Q2**Date:** 05/12/2022**REFERENCE**

Insured/Claimant: MSI INTEGRATED PTE LTD Policy No: DMCG21012341  
Date of Loss: 22/08/2022 Nature of Claim: OD Claim No: CDMCG22001709

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **YN9333K**  
Make & Model: ISUZU NHR85AUE4A, 3.0 D R1 (M) Engine No: 4JJ12C3113  
Reg. Date: 06/10/2015 (Man. Year: 2015) Chassis No: JAANHR85EF7100279  
Colour: Blue Odometer: 0 km  
Engine Capacity: 2999 cc  
Market Value/New Car Price: S\$30,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195/75 R15 Rear Tyre Size: 195/75 R15  
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm  
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,158.50	0.00	10,158.50	100.00
Miscellaneous Items	12,793.00	10,621.00	2,172.00	16.98
Labour	11,230.00	4,600.00	6,630.00	59.04
Paintwork Labour	0.00	0.00	0.00	
Towing	80.00	0.00	80.00	100.00
<b>Calculated Gross Total (S\$)</b>	<b>34,261.50</b>	<b>15,221.00</b>	<b>19,040.50</b>	<b>55.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,200.00</b>		
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	33,761.50	11,700.00	22,061.50	65.35
<b>+ GST 7.00/7.00% (S\$)</b>	2,363.31	819.00	1,544.31	65.35
<b>Nett Amount (S\$)</b>	<b>36,124.81</b>	<b>12,519.00</b>	<b>23,605.81</b>	<b>65.35</b>

**INSPECTION**

Date of Assignment: 31/08/2022 Present Location: City Auto Pte Ltd (HQ)  
BLK 8, SIN MING IND. ESTATE  
#01-60/62  
Date Inspected: 31/08/2022 Inspected At: Sector C  
SINGAPORE 575643.  
Repairer: City Auto Pte Ltd (HQ)  
Estimated Period of Repair: 14.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Dec 2022)	
<b>Parts:</b>	N/A	ISUZU NHR85AUE4A 3.0 D R1 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YN9333K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*Cabin front mounting bracket, LH & RH	Not Necessary	450.00 F	*- F
2	1		*Torsion bar lever	Not Necessary	330.00 F	*- F
3	1		*Torsion bar, upper	Not Necessary	165.00 F	*- F
4	1		*Charge air cooler	Not Necessary	860.00 F	*- F
5	1		*Radiator	Not Necessary	1,350.00 F	*- F
6	1		*Radiator fan guide	Not Necessary	180.00 F	*- F
7	1		*Cooling fan	Not Necessary	260.00 F	*- F
8	1		*Air con condenser	Not Necessary	600.00 F	*- F
9	1		*Air con condenser housing	Not Necessary	500.00 F	*- F
10	1		*Air con compressor	Not Necessary	700.00 F	*- F
11	2		*Cabin rear mounting bracket, LH & RH	Not Necessary	630.00 F	*- F
12	2		*Cabin rear mounting upper rubber cushion	Not Necessary	100.00 F	*- F
13	2		*Cabin rear mounting bracket upper	Not Necessary	110.00 F	*- F
14	1		*Engine control unit	Not Necessary	3,000.00 F	*- F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>9,235.00</b>	<b>0.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	923.50	0.00
<b>Total Parts (\$\$)</b>	<b>10,158.50</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	2	<b>Aluminium box, front panel aluminium sheets</b> (BENT)	900.00	900.00
2	2	<b>Aluminium box, side support pole, LH &amp; RH</b> (BENT)	700.00	700.00
3	2	<b>Aluminium box, sliding door assy, LH &amp; RH</b> (NOT NECESSARY)	1,200.00	0.00
4	1	<b>Brake oil</b> (NECESSARY)	18.00	18.00
5	1	<b>Clutch oil</b> (NECESSARY)	18.00	18.00
6	1	<b>IU bracket sticker</b> (NECESSARY)	5.00	5.00
7	4	<b>Power steering oil</b> (NECESSARY)	72.00	30.00
8	1	<b>Radiator coolant</b> (12 PCS) (NECESSARY)	180.00	50.00
9	1	<b>Rear deck front support frame</b> (BENT)	1,200.00	900.00
10	1	<b>Used cabin assy</b> (DENTED)	8,500.00	8,000.00
<b>Sub Total (\$\$)</b>			<b>12,793.00</b>	<b>10,621.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	<b>Remove damaged cabin and replace used cabin, front &amp; rear cabin mounting, charge air cooler, radiator &amp; other damaged parts, realignment etc.</b>	New	4,200.00	1,800.00
2	<b>Remove and install engine &amp; gearbox, to jack, straighten and realign chassis frame</b>	New	2,500.00	0.00
3	<b>To cut and remove aluminium box damaged panel &amp; poles, replace and welding new panel. Including jack and realign whole aluminium box</b>	New	2,000.00	1,000.00
4	<b>Remove and replace air con condenser and relevant parts. Vacuum and replenish air con gas</b>	New	180.00	150.00
5	<b>Computer diagnose and resetting, including programming ECU</b>	New	350.00	100.00
6	<b>Spray painting cabin and rear box</b>	New	1,800.00	1,400.00
7	<b>Logo writing for front cabin, include LGV sticker</b>	New	200.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,230.00</b>	<b>4,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >