



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 2970A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	BUCKLED	785.90	566.90
2	REAR BUMPER SIDE RETAINER (CONSISTENT)	O/S DISTORTED	74.40	37.20
2	REAR BUMPER REFLECTOR (CONSISTENT)	NO SUCH PARTS	123.80	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR BUMPER INNER FOAM (CONSISTENT)	CRACKED	103.00	103.00
1	RH TAILLAMP (CONSISTENT)	CUT	235.20	235.20
1	REAR TAILGATE (CONSISTENT)	BENT	1,981.20	1,659.00
1	REAR TAILGATE TOP CENTRE 'NISSAN' LOGO (CONSISTENT)	NECESSARY	64.90	64.90
1	REAR TAILGATE LH 'NV 200' EMBLEM (CONSISTENT)	NECESSARY	94.40	94.40
1	REAR TAILGATE LH 'VANETTE' EMBLEM(CONSISTENT)	NECESSARY	87.90	87.90
1	REAR TAILGATE TOP LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	287.10	-
1	REAR TAILGATE WEATHERSTRIP (CONSISTENT)	SERVICEABLE	97.40	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR END PANEL OUTER (CONSISTENT)	BENT	380.00	380.00
1	REAR END PANEL INNER (CONSISTENT)	TO REPAIR SEE LABOUR	690.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	98.80	-
	LESS 10% DISCOUNT		-519.40	-325.85
			4,674.60	2,932.65
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR TAILGATE LH '70KM/H' STICKER (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	REAR TAILGATE RH '6 PAX' STICKER (SN)(CONSISTENT)	NECESSARY	15.00	15.00
1	SET REVERSE SENSORS (SN)(CONSISTENT)	SCRATCHED	250.00	200.00
1	SET REAR END PANEL SEALANT (SN)(CONSISTENT)	NECESSARY	50.00	30.00
1	SET REAR WINDSCREEN SEALANT (SN)(CONSISTENT)	NECESSARY	50.00	40.00
			380.00	300.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	LABOUR CHARGES FOR REMOVE /REFIT ,PANEL BEATING ,CUTTING WELDING AND REPLACEMENT OF DAMAGES .INCLUSIVE OF THE REPAIR OF REAR TAILGATE TOP LOCK AND REAR END PANEL INNER .		1,000.00	600.00
	TO PUTTY & SPRAY SPRAY PAINTINGS CHARGES.		1,000.00	600.00
	TO REMOVE ,REFIT REAR TAILGATE WINDSCREEN GLASS .		140.00	120.00
	TO CHECK WIRINGS AND LIGHTINGS .		40.00	20.00
	TO REMOVE ,TRANSFER REAR TAILGATE FITTINGS .		80.00	60.00
	TO REPLACE REVERSE SENSORS & REVERSE CAMERA.		120.00	50.00
	TO APPLY ANTI RUST TREATMENT .		80.00	60.00
			2,460.00	1,510.00
	<b>GRAND TOTAL</b>		<b>7,514.60</b>	<b>4,742.65</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,742.65</b>

Report Ref No. CC4/ASM22008484/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.