

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008485/UPA3Q2
Date: 16/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001039470
Claimant Vehicle No :	SLX5363B	Insured Vehicle No :	XE4071H
Date of Loss:	30/08/2022	Nature of Claim:	TP
		Claim No:	202222006445

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX5363B	Engine No:	G4FGHH691498
Make & Model:	KIA CERATO K3, 1.6 (A)	Chassis No:	KNAFX411MJ5761691
Reg. Date:	29/03/2018 (Man. Year: 2017)	Odometer:	105296 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,859.40	4,850.87	3,008.53	38.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	2,150.00	2,220.00	50.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,229.40	7,000.87	5,228.53	42.75
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	12,229.40	5,600.00	6,629.40	54.21
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		33.00		
Nett Liability (S\$)		6,433.00		
Global Sum Settlement (S\$)		6,430.00		

INSPECTION

Date of Assignment:	31/08/2022	Zoom Autowerks Pte Ltd (HQ)
Date Inspected:	01/09/2022 Inspected At:	130 Bedok Reservoir Road, Eunos Spring, #08-1339
Estimated Period of Repair:	6.0 days	Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts: 143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLX5363B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	98.60 FL	*98.60 FL
2	1		*REAR TAILLAMP -LH	Not Necessary	487.60 FL	*- FL
3	1		*REAR BUMPER	Distorted	658.00 FL	*658.00 FL
4	1		*REAR BUMPER SIDE RETAINER (N/S)	Bent	38.50 FL	*38.50 FL
5	1		*REAR FENDER -LH	Badly Dented / Warped	889.60 FL	*889.60 FL
6	1		*REAR FENDER AIR GATE	Not Necessary	48.50 FL	*- FL
7	1		*REAR FENDER INNER SHIELD	Not Necessary	58.60 FL	*- FL
8	1		*REAR FUEL LID	Not Necessary	135.00 FL	*- FL
9	2		*REAR WHEEL HUB WITH BEARING	Damaged	560.00 FL	*560.00 FL
10	1		*REAR SHOCK ABSORBER	Twisted	221.60 FL	*221.60 FL
11	1		*REAR AXLE BEAM	Bent / Twisted	833.00 FL	*833.00 FL
12	1		*REAR DOOR -LH	Warped	935.00 FL	*935.00 FL
13	2		*REAR DOOR HINGES	Not Necessary	116.00 FL	*- FL
14	1		*REAR DOOR INNER BOARD	Not Necessary	622.00 FL	*- FL
15	1		*REAR DOOR LOCK	Not Necessary	300.00 FL	*- FL
16	1		*REAR DOOR OUTER HANDLE	Not Necessary	65.00 FL	*- FL
17	1		*REAR DOOR REGULATOR WITH SUPPORT	Not Necessary	453.00 FL	*- FL
18	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	351.00 FL	*- FL
19	1		*REAR DOOR WEATHERSTRIP	Not Necessary	145.00 FL	*- FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	45.00 FS	*- FS
23	1		*REAR TYRE (N/S) (LOCAL PURCHASE) (\$200.00) (60%)	Cut	400.00 FS	*120.00 FS
24	2		*REAR WHEEL RIMS	Cut / Warped	850.00 FS	*800.00 FS
25	1		*REAR DOOR BLACK TAPE (N/S)	Necessary	120.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,561.00	5,274.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	701.60	423.43
Total Parts (\$\$)	7,859.40	4,850.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	180.00	60.00
5	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	350.00	200.00
6	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
8	TO APPLY UNDERCOATING	New	200.00	60.00
9	PANEL BEATING	New	1,500.00	680.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	800.00
Gross Labour Cost (S\$)			4,370.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >