

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

AXA INSURANCE PTE LTD	PRE-REPAIR INSPECTION REPORT						
SINGAPORE 068811 ATTN: KHOR SAW THENG Code: ASM		AXA INSURANCE F	PTE LTD	F	Ref:	CS3/ASM22008486/Tcy3m4	
Insured Veh. SHA 5048E			Γ	Date:	26/09/2022		
Insured Veh. SHA 5048E		ATTN: KHOR SAW	THENG	C	Code:	ASM	
Policy No. VFX/P2419138 Coverage (\$) 0.00	1.	Policy Particulars :- (THIRD PARTY CLAIM)					
Claim No. S2M049W0 Excess (\$) 0.00 Assign From KHOR SAW THENG Assign Date 31/08/2022 2. Vehicle Particulars & Condition Make & Model MAZDA 3 C.C 1496 Engine No. HIDDEN Year of Reg. 2014 Chassis No. JM6BM42A8E0122374 Colour RED Odometer 127264 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres		Insured Veh.	SHA 5048E	Veh. Inspected		SFM 1232B	
Assign From KHOR SAW THENG Assign Date 31/08/2022 Vehicle Particulars & Condition Make & Model MAZDA 3		Policy No.	VFX/P2419138	Coverage (\$)		0.00	
Make & Model MAZDA 3		Claim No.	S2M049W0	Excess (\$)		0.00	
Make & Model MAZDA 3		Assign From	KHOR SAW THENG	Assign Date		31/08/2022	
Engine No. HIDDEN Year of Reg. 2014 Chassis No. JM6BM42A8E0122374 Colour RED Odometer 127264 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Nake Balance	2.		Vehicle Parti	culars & Condition	on		
Chassis No. JM6BM42A8E0122374 Colour RED Odometer 127264 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Make & Model	MAZDA 3	c.c		1496	
Odometer 127264 KM Steering IN ORDER		Engine No.	HIDDEN	Year of Reg.		2014	
Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Chassis No.	JM6BM42A8E0122374	Colour		RED	
General GOOD 3. Conditions of Tyres Size		Odometer	127264 KM	Steering		IN ORDER	
3. Conditions of Tyres Size		Brakes	IN ORDER	Modification		SPORTS RIM	
R/H Front Tyre 225/35 R19 FALKEN 6 mm L/H Front Tyre 225/35 R19 FALKEN 6 mm R/H Rear Tyre 225/35 R19 FALKEN 6 mm L/H Rear Tyre 225/35 R19 FALKEN 6 mm L/H Rear Tyre 225/35 R19 FALKEN 6 mm L/H Rear Tyre 225/35 R19 FALKEN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. 5. General Information Accident Date 28/08/2022 Inspect Date / Time 31/08/2022 (05:00 PM) Survey held at TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIRE STIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000		General	GOOD				
R/H Front Tyre 225/35 R19 FALKEN 6 mm L/H Front Tyre 225/35 R19 FALKEN 6 mm R/H Rear Tyre 225/35 R19 FALKEN 6 mm L/H Rear Tyre 225/35 R19 FALKEN 6 mm L/H Rear Tyre 225/35 R19 FALKEN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. 5. General Information Accident Date 28/08/2022 Inspect Date / Time 31/08/2022 (05:00 PM) Survey held at TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIRE STIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair	3. Conditions of Tyres						
L/H Front Tyre 225/35 R19			Size	Make		Balance	
R/H Rear Tyre 225/35 R19 FALKEN 6 mm L/H Rear Tyre 225/35 R19 FALKEN 6 mm 4.		R/H Front Tyre	225/35 R19	FALKEN		6 mm	
L/H Rear Tyre 225/35 R19 FALKEN 6 mm 4.		L/H Front Tyre	225/35 R19	FALKEN		6 mm	
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. 5. General Information Accident Date 28/08/2022 Inspect Date / Time 31/08/2022 (05:00 PM) Survey held at TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair		R/H Rear Tyre	225/35 R19	FALKEN		6 mm	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. 5. General Information Accident Date 28/08/2022 Inspect Date / Time 31/08/2022 (05:00 PM)		L/H Rear Tyre	225/35 R19	FALKEN		6 mm	
5. General Information Accident Date 28/08/2022 Inspect Date / Time 31/08/2022 (05:00 PM) Survey held at TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair	4. Description of Damages						
Accident Date 28/08/2022 Inspect Date / Time 31/08/2022 (05:00 PM) Survey held at TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair					AND		
Survey held at TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair	5.	General Information					
53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair		Accident Date	28/08/2022	Inspect Date / Ti	ime	31/08/2022 (05:00 PM)	
5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair		Survey held at	TRI KING AUTO SOLUTIONS P	TE LTD			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair			PAYA UBI INDUSTRIAL PARK				
BÍ THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000 5b. Estimate Days of Repair	5a.	Remarks					
,		B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000					
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days	5b.	· · ·					
· · ·		ESTIMATED NORM	MAL PERIOD FOR REPAIR:	7	7 Worki	ng Days	

Report Ref No. CS3/ASM22008486/Tcy3m4

Inspected By

MOHAMAD TAUFIKH

Automotive Assessor

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.